

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
1/1 Surp &
Resurvey After Paint
Today

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____ Third Party

Date: 04.09.2020

Accident Date : 03.09.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Estima" Reg. No. SKT947H Claiming Against Your Insured Reg. No. SMD9404J			
1pc	Tailgate		<i>B</i> 1,635.00 ✓
1pc	Tailgate Glass Moulding		<i>ne</i> 95.00 ✓
1pc	Tailgate Emblem		<i>ne</i> 73.00 ✓
1pc	Tailgate Badge Estima		<i>ne</i> 48.00 ✓
1pc	Tailgate Badge Aeras		<i>ne</i> 56.00 ✓
1pc	Tailgate Outer Moulding		<i>pu</i> 226.00 X
1pc	Tailgate Lock		<i>ne</i> 425.00 ✓
1pc	Tailgate Lock Catch		<i>dit</i> 58.70 ✓
1pc	Tailgate Weatherstrip		<i>nd/ht</i> 358.00 <i>507m</i>
1pc	Tailgate Stopper		<i>mrj</i> 14.00 ✓
1pc	Tailgate Trim Board		<i>mycm</i> 524.00 ✓
1pc	Tailgate Trim Board Clips	3.80	<i>ne</i> 38.00 ✓
1pc	Tailgate Inner Handle Grip		<i>mrj</i> 48.00 ✓
1pc	Tailgate Lock Cover		<i>mrj</i> 55.00 ✓
1pc	Rear Bumper	3.80	<i>pu</i> 595.00 ✓
1pc	Rear Bumper Clips		<i>ne</i> 38.00 ✓
1pc	Rear Bumper Top Retainer LH	102.00	<i>dit</i> 54.00 ✓
2pcs	Rear Bumper Brackets		204.00 ?
1pc	Rear Bumper Inner Boot Sensor		245.00 ?
1pc	Rear Bumper Corner Retainer LH	105.00	<i>dit</i> 40.00 ✓
2pcs	Rear Bumper Sponges		<i>nsp</i> 210.00 X
1pc	Rear Bumper Tow Cover		<i>pu</i> 26.00 X
1pc	Rear Bumper Reflector		<i>cm</i> 75.00 ✓
1pc	Taillamp LH		<i>cm</i> 409.00 ✓
1pc	End Panel		<i>B</i> 677.00 ✓
1pc	End Panel Inner Panel		302.00 ?
1pc	End Panel Top Garnish		<i>mycm</i> 286.00 ✓
1pc	End Panel Lower Garnish		<i>mycm</i> 301.00 ✓
2pcs	Rear Fender Trim Boards	740.00	<i>cm</i> 1,480.00 ✓
1pc	Spare Tyre Top Board		<i>cm</i> 855.00 ✓
Less 25%			9,450.70
			2,362.68
			7,088.03
			<i>ne</i> 50.00 SN
			<i>ne</i> 30.00 SN ✓
			<i>ne</i> 50.00 SN ✓
			<i>B</i> 45.00 SN ✓
			<i>Short</i> 280.00 SN
C/F			7,543.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 04.09.2020

Accident Date : 03.09.2020

承接汽车烧焊喷漆及
代理各种车辆赔偿

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Estima" Reg. No. SKT947H Claiming Against Your Insured Reg. No. SMD9404J		
		B/F	7,543.03
	To Dismantle / Transfer Tailgate Fittings / Ancillary Accessories		150.00 601
	To Dismantle / Refit Tailgate Glass		160.00 1201
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 ✓
	To Supply End Panel Body Sealant		60.00 301
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module etc.		120.00 501
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 601
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel, Floor Panel, Rear N/S Fender etc. Cnt, Weld End Panel and Parts Replacement		1,200.00 7001
	To Respray Affected Areas		1,000.00 8001
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas		350.00 ?
		Total :	10,763.03