

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised
61 Days @ 6600h
Resurvey After Paint
7 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Date: **04.09.2020**

Accident Date : 03.09.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Estima" Reg. No. SKT947H Claiming Against Your Insured Reg. No. SMD9404J		
1pc	Tailgate		R 1,635.00 ✓
1pc	Tailgate Glass Moulding		M 95.00 ✓
1pc	Tailgate Emblem		M 73.00 ✓
1pc	Tailgate Badge Estima		M 48.00 ✓
1pc	Tailgate Badge Aeras		M 56.00 ✓
1pc	Tailgate Outer Moulding		P 226.00 X
1pc	Tailgate Lock 371		N 425.00 ✓
1pc	Tailgate Lock Catch		D 58.70 ✓
1pc	Tailgate Weatherstrip		1795N D 358.00 50
1pc	Tailgate Stopper		M 14.00 ✓
1pc	Tailgate Trim Board		M 524.00 ✓
1pc	Tailgate Trim Board Clips	3.80	M 38.00 ✓
1pc	Tailgate Inner Handle Grip		M 48.00 ✓
1pc	Tailgate Lock Cover		M 55.00 ✓
1pc	Rear Bumper		B 595.00 ✓
1pc	Rear Bumper Clips	3.80	M 38.00 ✓
1pc	Rear Bumper Top Retainer LH		D 54.00 ✓
2pcs	Rear Bumper Brackets	102.00	R 204.00 X
1pc	Rear Bumper Inner Boot Sensor		R 245.00 ✓
1pc	Rear Bumper Corner Retainer LH		D 40.00 ✓
2pcs	Rear Bumper Sponges	105.00	N 210.00 X
1pc	Rear Bumper Tow Cover		S 26.00 X
1pc	Rear Bumper Reflector		C 75.00 ✓
1pc	Taillamp LH		C 409.00 ✓
1pc	End Panel		R 677.00 ✓
1pc	End Panel Inner Panel		N 302.00 X
1pc	End Panel Top Garnish		M 286.00 ✓
1pc	End Panel Lower Garnish		M 301.00 ✓
2pcs	Rear Fender Trim Boards	740.00	C 1,480.00 ✓
1pc	Spare Tyre Top Board		C 855.00 ✓
	Less 25%		9,450.70
			2,362.68
			7,088.03
	Tailgate Glass Sealant		M 50.00 SN
	Tailgate Glass Sealer		M 30.00 SN
	Tailgate Glass Fastener		M 50.00 SN
	Rear Number Plate		R 45.00 SN
	Rear Bumper Reverse Sensor		shot 200SN 280.00 SN
		C/F	7,543.03

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **04.09.2020**

Accident Date : 03.09.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Estima" Reg. No. SKT947H Claiming Against Your Insured Reg. No. SMD9404J		
		B/F	7,543.03
	To Dismantle / Transfer Tailgate Fittings / Ancillary Accessories		150.00 <i>600</i>
	To Dismantle / Refit Tailgate Glass		160.00 <i>1200</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 <i>✓</i>
	To Supply End Panel Body Sealant		60.00 <i>300</i>
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module etc.		120.00 <i>500</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>600</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel, Floor Panel, Rear N/S Fender etc. Cnt, Weld End Panel and Parts Replacement		1,200.00 <i>7000</i>
	To Respray Affected Areas		1,000.00 <i>8000</i>
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas	<i>nn</i>	<i>(Bill)</i> 350.00 <i>700</i>
	Total :		10,763.03