

# YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6  
#02-19 SINGAPORE 417883  
TEL: 6 5090052 FAX: 6 7479402

08-09-20

OUR REF NO. SJY 8773A

TAN KIM CHUAN  
BLK 120B, EDGEDALE PLAINS  
#14-293  
SINGAPORE 822120

ESTIMATE BILL FOR VEHICLE NO. SJY 8773A  
MODEL : KIA CERATO FORTE

LIST ITEM

1) BOOT LID		\$ 843.50	HC ✓
2) BOOT LID REFLECTOR	2 PCS @ \$ 283.00	\$ 566.00	Xnn ✓
3) BOOT LID WEATHERSTRIPE		198 \$ 247.20	hi ✓
4) BOOT LID BADGE		\$ 48.00	uey ✓
5) BOOT LID EMBLEM ' CERATO '		\$ 52.00	uey ✓
6) BOOT LID EMBLEM ' FORTE '		\$ 52.00	uey ✓
7) BOOT LID EMBLEM ' C.C '		\$ 50.20	uey ✓
8) BOOT LID STOPPER	2 PCS @ \$ 10.50	\$ 21.00	uey ✓
9) BOOT LID HINGE	2 PCS @ \$ 247.30	\$ 494.60	Ry ✓
10) BOOT LID LOCK		\$ 286.00	bt ✓
11) BOOT LID STRIKER		\$ 32.00	Ry ✓
12) BOOT LID INNER LINNING		\$ 281.00	Xnn ✓
13) BOOT LID INNER LINNING CLIP	9 PCS @ \$ 6.50	\$ 58.50	uey ✓
14) TAIL LAMP ASSY	2 PCS @ \$ 386.50	\$ 773.00	? uey ✓
15) TAIL LAMP BASE PANEL	2 PCS @ \$ 253.00	\$ 506.00	Ry ✓
16) TAIL LAMP CLIP	2 PCS @ \$ 10.50	\$ 21.00	? uey ✓
17) REAR BUMPER		695 \$ 731.00	dl ✓
18) REAR BUMPER SPONGE		\$ 256.00	uey ✓
19) REAR BUMPER CLIP	8 PCS @ \$ 6.50	\$ 52.00	uey ✓
20) REAR BUMPER SIDE ATTACHMENT	2 PCS @ \$ 68.00	\$ 136.00	dl ✓
21) REAR BUMPER LOWER SPOILER		\$ 1,321.00	uey ✓

# YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6  
 #02-19 SINGAPORE 417883  
 TEL: 6 5090052 FAX: 6 7479402

22)	REAR BUMPER REINFORCEMENT		\$	461.00	can - photo
23)	REAR BUMPER REINFORCEMENT BRACKET	2 PCS @ \$ 171.00	\$	342.00	X un
24)	REAR BUMPER REINFORCEMENT PLASTIC BRACKET	3 PCS @ \$ 52.00	\$	156.00	X un
25)	REAR BUMPER SPLASH SHIELD	2 PCS @ \$ 78.00	\$	156.00	78 LH-RH X un
26)	REAR BUMPER SPLASH SHIELD CLIP	6 PCS @ \$ 6.50	\$	39.00	19.50 LH-RH X un
27)	REAR END PANEL		\$	648.00	418.20 bt - photo.
28)	REAR PANEL INNER GARNISH		\$	186.00	de - photo.
29)	SPARE TYRE BOARD		\$	249.00	X un
30)	SPARE TYRE PANEL		\$	687.00	Rx photo.
31)	SAPRE TYRE NUT		\$	38.00	X un
32)	REAR CHASSIS MEMBER	2 PCS @ \$ 601.25	\$	1,202.50	X un
33)	REAR FENDER	2 PCS @ \$ 1513.00	\$	3,026.00	Rx
34)	REAR FENDER INNER BOARD	2 PCS @ \$ 289.30	\$	578.60	X un
35)	REAR FENDER INNER BOARD CLIP	10 PCS @ \$ 6.50	\$	65.00	X un
36)	REAR WINDSCREEN MOULDING		\$	151.00	X un
				\$ 14,813.10	
				\$ 1,481.31	
				\$ 13,331.79	
					5354.90
					4819.40

LESS DISCOUNT - 10%

## SPECIAL NETT ITEM

1)	REAR LICENCE PLATE (EMBOSS)		\$	55.00	X
2)	SPARE TYRE PANEL INSULATOR CLOTH		\$	350.00	X
3)	REAR WINDSCREEN INNERSEAL		\$	60.00	X
4)	REAR WINDSCREEN GUM		\$	60.00	X
			\$	525.00	

# YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6  
 #02-19 SINGAPORE 417883  
 TEL: 6 5090052 FAX: 6 7479402

## LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	\$ 50.00	30
2) TO APPLY UNDER SEALING ON AFFECTED AREAS	\$ 120.00	40.
3) TO MOUNT VEHICLE ON CAR O - LINER	\$ 380.00	? 250 plus 200 plus 40.
4) TO REMOVE AND REFIX REAR WINDSCREEN	\$ 320.00	X un
5) TO REMOVE AND REFIX PETROL TANK, PIPING SYSTEM, BRACKET AND ETC	\$ 220.00	X un
6) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	\$ 220.00	60.
7) TO REMOVE AND REFIX REVERSE CAMERA WITH WIRE HARDNESS	\$ 180.00	30.
8) TO REMOVE AND REFIX REAR EXHAUST SILENCER	\$ 180.00	* X un.
9) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY AND ETC	\$ 220.00	60.
10) TO REPLACE NEW PART, CUT, WELD, KNOCK ETC	\$ 4,180.00	1000
11) TO RESPRAY ON EFFECTED AREAS	\$ 2,200.00	1200
		\$ 8,270.00
<b>GRAND TOTAL</b>	<b>2620</b>	<b>\$ 22,126.79</b>

4819.40

2620

7439.41

45 \$ 5950 #

6 days

Tanpin 97495749  
 'WP' 2/9/20 @ Spr

ump sm

Resurvey after repair

6-7 days

Tanpin @ LKK auto. on.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: