

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Sep 2020 Sendback Est	07 Sep 2020 16:11 S\$5,421.64	08 Sep 2020 08:55 Edit Adj Rpt	S\$3,444.52 Edit Estimates	S\$3,444.52 View Rpt		Pending for Survey Report Cancel Case
Supp #1	08 Sep 2020 10:14	08 Sep 2020 10:15 S\$1,016.40	08 Sep 2020 10:15			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	A&L LEASING PTE LTD , Co. Reg. No.: 201026256R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHA1951Z	Date of Loss:	05/09/2020 00:00 - :59 [26 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2004397	Policy/Cover Note No.:	MJ001890 (Third Party Only) Coverage: 23/12/2019 - 22/12/2020
Vehicle Reg. No. (Insured):	YM7621Y	Policy No. (Claimant):	
		Excess:	S\$2,500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/09/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA1951Z (M2004397)
[YM7621Y]
TP
CTPL
Sep 5 2020 12:00AM
[A&L LEASING PTE LTD]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	07/09/20 16:11	Repairer Estimates		Load HTM
2	08/09/20 10:15	Repairer Estimates Suppl. #1		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/09/20 16:05	Adjuster Immediate Advice		Load HTM

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/09/20 13:59	Odometer Reading		Load JPG ☒
2	09/09/20 13:59	Chassis Number		Load JPG ☒
3	09/09/20 13:59	General View		Load JPG ☒
4	09/09/20 13:59	General View		Load JPG ☒
5	09/09/20 13:59	General View		Load JPG ☒
6	09/09/20 13:59	General View		Load JPG ☒
7	09/09/20 13:59	General View		Load JPG ☒
8	09/09/20 13:59	General View		Load JPG ☒
9	09/09/20 13:59	General View		Load JPG ☒
10	09/09/20 13:59	General View		Load JPG ☒
11	09/09/20 13:59	General View		Load JPG ☒
12	09/09/20 13:59	General View		Load JPG ☒
13	09/09/20 13:59	General View		Load JPG ☒
14	09/09/20 13:59	General View		Load JPG ☒
15	09/09/20 13:59	General View		Load JPG ☒
16	09/09/20 13:59	General View		Load JPG ☒
17	09/09/20 13:59	General View		Load JPG ☒
18	09/09/20 13:59	Reinspection Photo		Load JPG ☒
19	09/09/20 13:59	Reinspection Photo		Load JPG ☒
20	09/09/20 13:59	Reinspection Photo		Load JPG ☒
21	09/09/20 13:59	Reinspection Photo		Load JPG ☒
22	09/09/20 13:59	Reinspection Photo		Load JPG ☒
23	09/09/20 13:59	Reinspection Photo		Load JPG ☒
24	09/09/20 13:59	Reinspection Photo		Load JPG ☒
25	09/09/20 13:59	Reinspection Photo		Load JPG ☒
26	09/09/20 13:59	Reinspection Photo		Load JPG ☒
27	09/09/20 13:59	Reinspection Photo		Load JPG ☒
28	09/09/20 13:59	Reinspection Photo		Load JPG ☒
29	09/09/20 14:00	Replacement Part Photo		Load JPG ☒
30	09/09/20 14:00	Replacement Part Photo		Load JPG ☒
31	09/09/20 14:00	Replacement Part Photo		Load JPG ☒

Documentation			1 per page ▼	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail Print
1	14/09/20 17:21	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF

Assessment Reports				1 per page ▾	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	07/09/20 16:12	E-filed GIA report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

ResetSavePrint

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI20009591/T1TF3S2**Date:** 15/09/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ001890		
Claimant Vehicle No :	SHA1951Z	Insured Vehicle No :	YM7621Y		
Date of Loss:	05/09/2020	Nature of Claim:	TP	Claim No:	M2004397

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1951Z		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEJU046148
Reg. Date:	05/07/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVJU103449
Colour:	Blue	Odometer:	250947 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,527.04	2,913.52	2,613.52	47.29
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	900.00	520.00	380.00	42.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,438.04	3,444.52	2,993.52	46.50
+ GST 7.00/7.00% (S\$)	450.66	241.12	209.54	46.50
Nett Amount (S\$)	6,888.70	3,685.64	3,203.06	46.50

INSPECTION

Date of Assignment:	08/09/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	07/09/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Sep 2020)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1951Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER	Cracked	418.30 FL	-	*418.30 FL
2	1		*RADIATOR GRILLE	Cracked	1,409.10 FL	-	*1,409.10 FL
3	1		*FRT BUMPER CTR MOULDING	Cut	188.00 FL	-	*188.00 FL
4	1		*FRT BUMPER AIR FLAP UPR RH/LH	N/s Cracked/O/s Not Necessary	712.00 FL	-	*356.00 FL
5	1		*SMART CRUISE CONTROL	Not Necessary	2,910.90 FL	-	*- FL
Supplementary #1							
6	1		*FRT BUMPER CTR UPR MOULDING	Cracked	108.50 FL	-	*108.50 FL
7	1		*FRT BUMPER SPONGE	Deformed	86.90 FL	-	*86.90 FL
8	1		*FRT BUMPER REINFORCEMENT	Bent	1,075.10 FL	-	*1,075.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,908.80	3,641.90
- List Item Discount on L Items 20.00/20.00% (\$)	1,381.76	728.38
Total Parts (\$)	5,527.04	2,913.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAY PAINTING	New	300.00	200.00
3	DIA/RESET SMART CRUISE CONTROL	New	200.00	0.00
Gross Labour Cost (\$\$)			900.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >