

TO : **NTUC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBG7638D**
 MODEL : **NISSAN CABSTAR**
 DATE OF ACCIDENT : 05.09.20
 TIME OF ACCIDENT : 12:20HRS

27	REAR SPARE TYRE REGULATOR GEAR <i>NE m</i>	1	\$ 356.70	\$ 356.70
----	--	---	-----------	-----------

7970.40
7173.36

TOTAL PRICE	\$ 15,834.80
LESS 10%	\$ 1,583.48
SUB TOTAL PRICE	\$ 14,251.32

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00
2	FRONT GRILLE CLIP (SET) <i>NE m</i>	1	\$ 30.00	\$ 30.00
3	FRONT PANEL SEALANT <i>NE m</i>	1	\$ 80.00	\$ 80.00
4	HEAD LAMP LOWER GARNISH CLIP (SET) <i>NE m</i>	1	\$ 30.00	\$ 30.00
5	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00
6	SIDE GATE COVER ALUMINIUM LH (SPECIAL TYPE) <i>3 m</i>	1	\$ 680.00	\$ 680.00
7	TAIL GATE COVER ALUMINIUM (SPECIAL TYPE) <i>3 m</i>	1	\$ 480.00	\$ 480.00
8	TAIL GATE '70KM/H' STICKER <i>3 m</i>	1	\$ 40.00	\$ 40.00
9	TAIL GATE '13 PAX' STICKER	1	\$ 40.00	\$ 40.00
10	TAIL LAMP CLIP (SET) <i>NE m</i>	1	\$ 60.00	\$ 60.00
11	REAR END PANEL SEALANT <i>NE m</i>	1	\$ 80.00	\$ 80.00
12	REAR FLOOR COVER ALUMINIUM (SPECIAL TYPE) <i>NE m</i>	1	\$ 2,800.00	\$ 2,800.00
13	REAR SPARE TYRE (BIG) <i>NE m</i>	1	\$ 350.00	\$ 350.00
14	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

310. TOTAL \$ 5,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,200.00	<i>800.</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,200.00	<i>400.</i>
3	TO SPRAY TUFF COAT	\$ 280.00	<i>X</i>
4	WIRING, BULB CHECKING	\$ 150.00	<i>30</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 150.00	<i>X</i>
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>X</i>

TO : **NTUC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBG7638D**
 MODEL : **NISSAN CABSTAR**
 DATE OF ACCIDENT : 05.09.20
 TIME OF ACCIDENT : 12:20HRS

7	REFOCUS HEADLAMP BEAM	\$ 60.00	X
8	REMOVE AND REFIX AIRCON CONDENSER, AIR CON BLOWER, AIR CON COOLING COIL AND REFILL AIRCON GAS	\$ 650.00 200.	
9	REMOVE AND REFIX AUDIO SYSTEM	\$ 200.00	X
10	REMOVE AND REFIX FRONT DASHBOARD	\$ 850.00 200	

1630

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,600.00	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	600.
3	REMOVE AND REFIX REAR CROSS MEMBER AND REAR CHASSIS ALIGHMENT	\$ 450.00	X
4	REMOVE AND REFIX REAR RAILING	\$ 380.00	X
5	REMOVE AND REFIX REAR FLOOR COVER ALUMINIUM	\$ 1,200.00	X
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00 50	
7	REMOVE AND REFIX CANOPY	\$ 1,200.00	X

1250.

TOTAL \$ 10,400.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,251.32
 TOTAL LABOUR COST : \$ 10,400.00
 TOTAL REPAIR COST : \$ 24,651.32

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian
 L/S 08/09/20.
 09 Days.
 Total: 10363.36
 L/S: 8.21c.