

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 116/IC/TCAC/SAY/2020
DATE : 05-SEP-2020

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR LIM BING LIANG MAX (LIN BINGLIANG)
ADDRESS : BLK 29 GHIM MOH LINK
#38-320
S(270029)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1900010807-01
VEHICLE NO : SMH6424A
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12260323J
CHASSIS NO : JN1TAAE12Z0982557
MILEAGE : 7618 KM
DATE IN : 05/09/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 04/09/2020

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS (OPC)(REAR)(SUPP)	60.00	60.00 / <i>suppl</i>
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
4 ZZ/001	CONDUCT TP CLAIM CMTAIPINGDATE:04/09/2020 TIME: 1750 LOCATION:SLIP RD TO AYE CITY N BOUNA VISTA RD		
5 ZZ/002	REPAIR/REPLACE REAR BUMPER,RR ENDPANEL,RR TAILGATE LH RR FENDER , RH RR FENDER& FLOORPAN(SUPP)	1680.00	1680.00 ✓
6 ZZ/003	RESPRAY REAR BUMPER,ENDPANEL, TAILGATE, LH RR FENDER, RH RR FENDER& FLOORPAN(SUPP)	1500.00	1500.00 ✓
7 ZZ/004	REMOVE/REFIX REAR WINDSCREEN	150.00	150.00
8 ZZ/005	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	144.00	144.00
9 ZZ/006	CHECK ALL LIGHTING AFTER REPAIR	48.00	48.00
10 ZZ/007	SUPPLY AND INSTALL REVERSE CAMERA	240.00	.00
11 ZZ/008	BREAKSEAL/RESEAL REAR OPC LICENCE PLATE AND SEND FOR VEHICLE INSPECTION(OPC)(SUPP)	120.00	120.00 / <i>suppl</i>
12 ZZ/009	REMOVE/REFIX REAR SEAT,UPHOLSERY,CARPET, TRIM & GARNISH TO FACILITATE REPAIR (SUPP)	280.00	280.00 / <i>suppl</i>
TOTAL LABOUR CHARGES		4377.00	4137.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH6424A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	ENERGY ABSORBER SPONGE (SUPP)	85090-5WJ0A	125.30			OK
2	ACTUATOR ASSY (SUPP) * short	90550-1HM0A	170.00			OK
3	BOX-LUGGAGE (SUPP)	84975-5WK1A	143.00			OK
4	FINISHER-LUGGAG (SUPP)	84951-5WKDA	396.40			OK
5	FINISHER-LUGGAG (SUPP)	84950-5WK0A	396.40			OK
6	CARPET-LUGGAGE (SUPP)	84903-5WK0A	433.70			OK
7	COVER-ARM, BACK WIPER (SUPP) ml	28782-1FCOA			13.10	OK
8	ARM ASSY-RR WDW (SUPP) * sc	28780-3VA0A			82.00	OK
9	MOTOR-WIPER (SUPP) * short	28710-3VA0A			427.30	OK
10	REAR NUMBER PLATE GARNISH (SUPP)	90810-3VA5C	255.60			OK
11	A LOCK LIFT REAR TAILGATE (SUPP)	90502-1HM1A	128.40			OK
12	PLATE-LUGGAGE BOOT INNER GARNISH (SUPP)	84992-3VA0A	68.80			OK
13	FACE-RR BUMPER	85022-5WJ0H	460.00			OK
14	PANEL REAR LWR (SUPP)	79100-3VA0B	552.80			OK
15	DOOR BACK TAILGATE	K010M-3VAMA	1018.20			OK
16	EMBLEM-BACK DOO LETTERING	90890-3VA0A	64.90			OK
17	ORNAMENT-BACK D EMBLEM	90892-3VADA	79.90			OK
18	GLASS-TAIL GATE	90300-3VA1C	1198.80			OK
19	BRKT BUMPER RH	85220-3VA0C	51.00			OK
20	BRKT BUMPER LH	85221-3VA0C	51.00			OK
21	CAMERA BRACKET-REPLACE RR WS (SUPP)	BRACKET-CAM			20.00	OK
22	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
23	LAMP COMB RR, RH (SUPP)	26550-5WK0A	435.80			OK
24	CLIP BUMPER	01553-10501	15.60			OK
25	LAMP COMB RR, LH (SUPP)	26555-5WK0A	435.80			OK

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SMH6424A

NETT ITEM 6481.40
LESS 20.00%) -1296.28
NETT AMOUNT 5185.12

LIST ITEM 0.00
LESS 30.00%) 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 622.40
LESS .00%) 0.00
SPECIAL NETT AMOUNT 622.40

TOTAL LABOUR CHARGES 4137.00
TOTAL SPARE PARTS CHARGES 5807.52

TOTAL CHARGES 9944.52
ADD 7 % GST 696.12

GRAND TOTAL 10640.64

DATE	TIME	DESCRIPTION	AMOUNT
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00
15/01/2015	10:00	REPAIR WORK	1000.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

CONSTRUCTION OF ROAD

REPAIR WORK

NOTICE NOTICE

REPAIR WORK

REPAIR WORK

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH6424A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
	SUB TOTAL		6481.40	0.00	622.40
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1296.28	0.00	0.00
	GRAND TOTAL		5185.12	0.00	622.40
	OVERALL TOTAL		5807.52		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED