

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 116/IC/TCAC/SAY/2020
DATE : 05-SEP-2020

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR LIM BING LIANG MAX (LIN BINGLIANG)
ADDRESS : BLK 29 GHIM MOH LINK
#38-320
S(270029)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1900010807-01
VEHICLE NO : SMH6424A
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12260323J
CHASSIS NO : JN1TAAE12Z0982557
MILEAGE : 7618 KM
DATE IN : 05/09/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 04/09/2020

AUTOCLINIC PTE LTD
 LENG KEE ROAD
 SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH6424A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	/
3	ZZ/001	CONDUCT TP CLAIM CMTAIPINGDATE:04/09/2020 TIME: 1750 LOCATION:SLIP RD TO AYE CITY N BOUNA VISTA RD		
4	ZZ/002	REPAIR/REPLACE REAR BUMPER,RR ENDPANEL,RR TAILGATE LH RR FENDER & RH RR FENDER	1400.00	840
5	ZZ/003	RESPRAY REAR BUMPER,ENDPANEL, TAILGATE, LH RR FENDER AND RH RR FENDER	1250.00	750
6	ZZ/004	REMOVE/REFIX REAR WINDSCREEN	150.00	/
7	ZZ/005	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	144.00	!
8	ZZ/006	CHECK ALL LIGHTING AFTER REPAIR	48.00	/
9	ZZ/007	SUPPLY AND INSTALL REVERSE CAMERA	240.00	?
TOTAL LABOUR CHARGES			3387.00	

AUTOCLINIC PTE LTD
 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH6424A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 FACE-RR BUMPER <i>See /</i>	85022-5WJOH	460.00		
2 PANEL REAR LWR ?	79100-3VA0B	552.80		
3 DOOR BACK TAILGATE <i>St /</i>	K010M-3VAMA	1018.20		
4 EMBLEM-BACK DOO LETTERING <i>see /</i>	90890-3VA0A	64.90		
5 ORNAMENT-BACK D EMBLEM <i>see /</i>	90892-3VA0A	79.90		
6 GLASS-TAIL GATE <i>1/2 photo? see /</i>	90300-3VA1C	1198.80		
7 ENERGY ABSORBER SPONGE ?	85090-5WJOA	125.30		
8 BRKT BUMPER RH <i>see /</i>	85220-3VA0C	51.00		
9 BRKT BUMPER LH <i>see /</i>	85221-3VA0C	51.00		
10 CAMERA BRACKET ?	BRACKET-CAM			20.00
11 REAR W/SCREEN SEALANT <i>see /</i>	SEALANT - 4			80.00
12 LAMP COMB RR,RH ?	26550-5WK0A	435.80		
13 PLATE-LUGGAGE BOOT INNER GARNISH ?	84992-3VA0A	68.80		
14 A LOCK LIFT REAR TAILGATE ?	90502-1HM1A	128.40		
15 REAR NUMBER PLATE GARNISH ?	90810-3VA5C	255.60		
16 CLIP BUMPER <i>see /</i>	01553-10501	15.60		
17 LAMP COMB RR,LH ?	26555-5WK0A	435.80		
SUB TOTAL		4941.90	0.00	100.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		988.38	0.00	0.00
GRAND TOTAL		3953.52	0.00	100.00
OVERALL TOTAL		4053.52		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOCLINIC PTE LTD
LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMH6424A

TOTAL LABOUR CHARGES	3387.00
TOTAL SPARE PARTS CHARGES	4053.52
GRAND TOTAL	7440.52 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010068
SURVEYED DATE	:	09/09/2020 @ 1030
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

6 days
Rerog before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: