

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009604/KES3Q2**Date:** 15/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100502195
Claimant Vehicle No :	SJY5924B	Insured Vehicle No :	SLL4264Z
Date of Loss:	27/08/2020	Nature of Claim:	TP
		Claim No:	4441163086SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY5924B	Engine No:	27295231600117
Make & Model:	MERCEDES-BENZ E300, 3.0 (A)	Chassis No:	WDD2120542A265552
Reg. Date:	16/09/2010 (Man. Year: 2010)	Odometer:	79604 km
Colour:	Metallic Brown		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Sumitomo 8 mm	Rear Left Side:	Sumitomo 8 mm
Front Right Side:	Sumitomo 8 mm	Rear Right Side:	Sumitomo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,263.20	4,014.00	1,249.20	23.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,445.00	815.00	630.00	43.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,708.20	4,829.00	1,879.20	28.01
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	6,708.20	3,850.00	2,858.20	42.61
+ GST 7.00/7.00% (S\$)	469.57	269.50	200.07	42.61
Nett Amount (S\$)	7,177.77	4,119.50	3,058.27	42.61
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,519.50		

INSPECTION

Date of Assignment:	08/09/2020	City Auto Pte Ltd (Sin Ming) (HQ)
Date Inspected:	08/09/2020 Inspected At:	Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est
Estimated Period of Repair:	3.0 days	Singapore 575643

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH TAILLAMP	Serviceable	738.00 FL	*- FL
2	1		*REAR BUMPER	Buckled	1,820.00 FL	*1,698.00 FL
3	1		*REAR BUMPER CHROME LH	Necessary	185.00 FL	*185.00 FL
4	1		*REAR BUMPER CHROME RH	Necessary	185.00 FL	*185.00 FL
5	1		*REAR BUMPER CHROME CENTRE	Necessary	215.00 FL	*215.00 FL
6	1		*REAR BUMPER SPONGE	No such part	162.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	910.00 FL	*910.00 FL
8	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	110.00 FL	*55.00 FL
9	1		*REAR BUMPER SIDE BRACKET	O/S Distorted	196.00 FL	*98.00 FL
10	1		*REAR BUMPER CENTER BRACKET	Repair	115.00 FL	*- FL
11	1		*REAR BUMPER LOWER LID	Distorted / Cracked	595.00 FL	*497.00 FL
12	12		*REAR BUMPER CLIPS	Necessary	108.00 FL	*108.00 FL
13	1		*REAR BOOT LOGO	Necessary	58.00 FL	*58.00 FL
14	1		*REAR BOOT EMBLEM -7G TRONIC	Necessary	66.00 FL	*66.00 FL
15	1		*REAR BOOT EMBLEM -E300	Necessary	98.00 FL	*98.00 FL
16	2		*REAR BUMPER LOWER BRACKET	Cracked	72.00 FL	*72.00 FL
17	1		*RH EXHAUST CHROME DIP	Dented	215.00 FL	*215.00 FL
					Sub Total (\$\$)	5,848.00 4,460.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	584.80 446.00
					Total Parts (\$\$)	5,263.20 4,014.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	80.00	80.00
2	TO CHECK WIRING AND LIGHTING	New	45.00	15.00
3	TO REMOVE AND REFIT EXHAUST MUFFLER	New	120.00	0.00
4	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	500.00	320.00
5	SPRAY PAINTING ON AFFECTED & RPELACE PARTS	New	700.00	400.00
Gross Labour Cost (\$\$)			1,445.00	815.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >