



Case Details

Case Reference Number : TAX/09/20/2009
Type of Repair : Accident Repair
Vehicle Registration Number : SHD6260K

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-12533-ID
Assigned By : Tan Lee Ge #

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 04/09/2020 02:10 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	977.80	977.80	25.00	733.35	Replace	1	733.35	Replace	✓ CR 4
One Time Key In	Main			LINER, FR FENDER, RH	1	202.50	202.50	25.00	151.88	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			RETAINER, FR WHEEL RH	1	3.20	3.20	25.00	2.40	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PROTECTOR, FR FENDER RH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PAD, FR WHEEL RH	1	59.60	59.60	25.00	44.70	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER , RH	1	979.40	979.40	25.00	734.55	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			WHEEL, DISC FRONT	1	1,879.40	1,879.40	25.00	1,409.55	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	668.90	668.90	25.00	501.67	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	211.50	211.50	25.00	158.63	Replace	0	0	Not Give	✓ X SVC

Total Spare Part Cost 5,967.23

Surveyor Total 774.30

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 5,967.23

Final Sur Total 774.30

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	108.60	108.60	25.00	81.45	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			COVER, FR BUMPER	1	521.00	521.00	25.00	390.75	Replace	1	0	Repair	✓ X R
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	80.10	80.10	25.00	60.07	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			MOULDING, FRONT BUMPER SIDE, RH	1	95.60	95.60	25.00	71.70	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	✓ / Nec
Total Spare Part Cost									5,967.23	Surveyor Total 774.30				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									5,967.23	Final Sur Total 774.30				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	507.00	200	✓
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	✓
Total:			1,116.00	400.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY RIM	180.00	0	
3	Main	TO REPSRAY FRONT BUMPER	378.00	200	
4	Main	RESPRAY MIRROR COVER RH	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
2	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			600.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,967.23	774.30
Total Labour Cost	507.00	200.00
Total Spray Painting	1,116.00	400.00
Other	600.00	80.00
Overall Total	8,190.23	1,454.30
Lump Sum Repair Option		☐
Lump Sum Total	0.00	1,454.30
Surveyor Approved Amount		1,454.30
No of Repair Days*	5	3 <i>days</i>
Remarks	-	P/P, Before paint photo


Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

04/09/2020

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: