



Section A - Accident Details

Registration Number	SHD6260K
Case Reference Number	TAX/09/20/2009
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SIM KENG LIM
Type of Accident	Side Swipe
Accident Date and Time	4/9/2020 10:10 AM
Accident Reported Date and Time	4/9/2020 11:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108064
Special Instruction to ARC, if any	RIGHT FRONT PORTION DAMAGE
Prepared Date and Time	4/9/2020 3:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$200.00
Total Spray Cost	\$0.00	\$400.00
Total Spare Part Cost	\$5,967.23	\$774.30
Total Other Cost	\$0.00	\$80.00
TOTAL COST	\$5,967.23	\$1,454.30 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	04/09/2020 3:19 PM	04/09/2020 3:28 PM
Signature		
Remarks		P/P, Before paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2009-0219	Invoice Number	
Quotation Date	16.09.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$507.00	\$200.00 ✓
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$600.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53801-47080	FENDER SUB-ASSY, FR, RH	1.00	\$977.80	25.00	\$733.35	Replace	Replace ✓
		53875-47120	LINER, FR FENDER, RH	0.00	\$202.50	0.00	\$0.00	Replace	Check X
		53857-12010	RETAINER, FR WHEEL RH	0.00	\$3.20	0.00	\$0.00	Replace	Not Given X
		53827-47050	PROTECTOR, FR FENDER RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given X
		53851-47061	PAD, FR WHEEL RH	0.00	\$59.60	0.00	\$0.00	Replace	Not Given X
		53701-47111	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$979.40	0.00	\$0.00	Replace	Check X
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,879.40	0.00	\$0.00	Replace	Not Given X
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$668.90	0.00	\$0.00	Replace	Not Given X
		42602-47251	CAP SUB-ASSY, WHEEL	0.00	\$211.50	0.00	\$0.00	Replace	Not Given X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		87910-47450	MIRROR ASSY, OUTER REAR VIEW, RH	0.00	\$1,436.60	0.00	\$0.00	Replace	Not Given X
		87915-47070-A1	COVER, OUTER MIRROR, RH	0.00	\$108.60	0.00	\$0.00	Replace	Not Given X
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	100.00	\$0.00	Replace	Repair ✓
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given X

Cru

SVC

SVC

SVC

SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/09/2020
User ID : PohSuan

		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.50	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace <input checked="" type="checkbox"/>
Total					\$7,586.24		\$774.30		

} SVC
Nec

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

774.30
+ 200.00
+ 480.00

1454.30