

RICO

AUTO
SERVICE

Rico 60 Auto Services Pte Ltd. B1K 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060
VEHICLE NUM: **SKF 2008 D**
MAKE & MODEL: **VOLKSWAGEN JETTA**
MILEAGE:
TYRE:
CHASSIS NUM:

ATTN	NO	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING X <i>NN</i>	1	
	2	BOOTLID X <i>R</i>	1	
	3	BOOTLID LOGO (VOLKSWAGEN) / <i>npc</i>	1	97
	4	BOOTLID EMBLEM (JETTA) / <i>npc</i>	1	72
	5	BOOTLID EMBLEM (TSI) / <i>npc</i>	1	54
	6	BOOTLID LAMP (L+R) CRH X <i>NN</i>	1	
	7	BOOTLID SWITCH X <i>NN</i>	1	
	8	BOOTLID CARPLATE LAMP X <i>NN</i>	2	
	9	BOOTLID LOCK X <i>NN</i>	1	
	10	BOOTLID LOCK CATCH X <i>NN</i>	1	
	11	BOOT LID INNER TRIM X <i>NN</i>	1	
	12	BOOT LID HINGE (L+R) X <i>NN</i>	2	
	13	BOOT LID DAMPER (L+R) X <i>NN</i>	2	
	14	BOOTLID STOPPER X <i>NN</i>	2	
	15	BOOTLID WEATHERSTRIP X <i>NN</i>	1	
	16	TAIL LAMP (L+R) <i>CRH</i> ? / <i>OR</i>	1	382
	17	TAIL LAMP PANEL (L+R) X <i>NN</i>	2	
	18	REAR BUMPER / <i>DD</i>	1	1196
	19	REAR BUMPER RETAINER (L+R) / <i>OR</i>	2	240
	20	REAR BUMPER REINFORCEMENT BAR ? / <i>RT</i>	1	494
	21	REAR BUMPER BRACKET (L+R) ? / <i>BR</i> (Tailp bar)	2	178
	22	REAR BUMPER CENTER BRACKET ? / <i>OR</i>	1	124
	23	REAR BUMPER SPONGE ? X <i>NN</i>	1	
	24	REAR BUMPER REVERSE SENSOR / <i>Shot</i>	2	200
	25	REAR BUMPER REFLECTOR (L+R) <i>CRH</i> ? / <i>OR</i>	12	66
	26	REAR BUMPER LOWER / <i>CRH</i>	1	583
	27	REAR BUMPER UNDERCOVER X / <i>OR</i>	1	84
	28	REAR FENDER (L+R) X <i>NN</i>	2	
	29	REAR FENDER INNER TRIM (L+R) X <i>NN</i>	2	
	30	REAR FENDER COWLING (L+R) X <i>NN</i>	2	
	31	END PANEL / <i>DD</i>	1	786
	32	END PANEL TOP GARNISH ? / <i>CRH</i>	1	175
	33	SPAREWHEEL PANEL X <i>R</i>	1	
	34	SPAREWHEEL PANEL TOP BOARD X <i>NN</i>	1	
	35	SPAREWHEEL PANEL TOP BOARD TOP MAT X <i>NN</i>	1	
	36	EXHAUST PIPE X <i>NN</i>	1	
	37	EXHAUST GASKET X <i>NN</i>	1	473
	38	EXHAUST BRACKET (L+R) X <i>NN</i>	2	-19%
	39	EXHAUST HEAT SHIELD X <i>NN</i>	1	4257.90

		SUBTOTAL	\$	-
		LESS 10%	\$	-
		PARTS TOTAL	\$	-
		SPECIAL NETT	QTY	PRICE
1	REAR WINDSCREEN SEALANT X N/A	1	\$	200.00
2	BOOTLID INNER TRIM CLIPS X N/A	10	\$	100.00
3	REAR CARPLATE X N/A	1	\$	120.00
4	REAR CARPLATE FRAME X N/A	1	\$	120.00
5	TAIL LAMP CLIPS X N/A	4	\$	80.00
6	TAIL LAMP PANEL SEALANT X N/A	2	\$	300.00
7	REAR BUMPER CLIPS ✓ MPC	10	\$	100.00 30
8	REAR FENDER SEALANT X N/A	2	\$	600.00
9	REAR FENDER INNER TRIM CLIPS X N/A	20	\$	200.00
10	REAR FENDER COWLING CLIPS X N/A	20	\$	200.00
11	END PANEL SEALANT ✓ MPC	1	\$	400.00 30
12	SPAREWHEEL PANEL SEALANT X N/A	1	\$	450.00 6
		SPECIAL NETT TOTAL	\$	2,870.00
		LABOUR	QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN 800	1	\$	3,600.00 600
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 1000	1	\$	2,700.00 800
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$	600.00 30
4	TO RNR REAR BOOT MECHANISM	1	\$	400.00 X
5	TO RNR REAR LUGGAGE COMPARTMENT	1	\$	400.00 50
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	1	\$	800.00 X
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	\$	150.00 30
8	TO CHECK WIRING LAYOUT AND BOOTLID LAMP	1	\$	150.00 X
9	TO CHECK WIRING LAYOUT AND TAIL LAMP	1	\$	150.00 X
10	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	1	\$	1,200.00 X
11	TO DO WATER LEAK TEST.	1	\$	100.00 30
12	TO RNR FUEL TANK TO ASSIST WORK LOAD	1	\$	450.00 X
		TOTAL	\$	10,700.00
		GRAND TOTAL COST	\$	13,570.00

Steve (LKK)

WML M/L

8/9/20, 3.30pm

6 B dys

L/S

Ry AL Sky

P- 4257-90

NI- 64

L- 1940

6257-90

L/S- 5006-32

= 5000

4K limit repair