



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2008219
INV Date 10/12/2020
Reference CC3/CTI20009615/Kes3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHF 754G
Insured Veh. SJF 7086G
Claim No. SNM20D203227
Policy No. DMPCSNW00055522002
Accident Date 03/09/2020
Inspection Date 07/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20009615/Kes3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 10-12-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 7086G	Veh. Inspected	SHF 754G
Policy No.	DMPCSNW00055522002	Coverage (\$)	0.00
Claim No.	SNM20D203227	Excess (\$)	0.00
Assign From		Assign Date	07/09/2020

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC283269	Colour	METALLIC WHITE / RED
Odometer	561921	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	BRIDGESTONE	8 mm
L/H Front Tyre	215/60 R16	BRIDGESTONE	8 mm
R/H Rear Tyre	215/60 R16	BRIDGESTONE	8 mm
L/H Rear Tyre	215/60 R16	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2020	Inspection Date	07/09/2020
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 754G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER COVER REAR	BUCKLED	561.70	561.70
1	BUMPER LOWER REAR	DENTED	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	CRACKED	16.60	16.60
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER BEAM REAR	BENT / DISTORTED	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	114.50	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	82.40	-
1	BOOT BADGE	NOT NECESSARY	95.80	-
	LESS 10% DISCOUNT		-572.74	-153.80
			5,154.62	1,384.20
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	75.00	75.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	65.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	50.00	-
1	SET BUMPER BRACKET SIDE CLIP RR (SN)	NOT NECESSARY	65.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	50.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	69.00	-

Report Ref No. CC3/CTI20009615/Kes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	75.00	75.00
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	TAILLAMP CLIP (SN)	NOT NECESSARY	45.00	-
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	180.00	30.00
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	60.00	-
			1,594.00	580.00
	LABOUR			
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL) AND BOOT REAR.		1,400.00	200.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	220.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			3,940.00	495.00
GRAND TOTAL			10,688.62	2,459.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CC3/CTI20009615/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 754G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

