

*Not Authorised*  
*1/1 Smp & 1950/-*  
*Mercury After Paint*  
 AAD2009-024

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 754G**

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

07 SEP 2020

**SHF 754G**

VF1ABL15AUC283269

RENAULT

LATITUDE

3.9.2020

**CHINA TAIPING**

30/6/2016

- |   | PART                              |
|---|-----------------------------------|
| 1 | BUMPER COVER REAR                 |
| 1 | BUMPER LOWER REAR                 |
| 1 | BUMPER BRACKET CTR REAR           |
| 1 | BUMPER BRACKET SIDE LH REAR       |
| 1 | BUMPER RETAINER LH REAR           |
| 1 | BUMPER REFLECTOR LH               |
| 1 | BUMPER BRACKET SIDE RH REAR       |
| 1 | BUMPER RETAINER RH REAR           |
| 1 | BUMPER BEAM REAR                  |
| 1 | BUMPER BEAM BRACKET LH REAR       |
| 1 | BUMPER BEAM BRACKET RH REAR       |
| 1 | OUTER PANEL REAR (End Panel)      |
| 1 | OUTER PANEL REAR (End Panel) TRIM |
| 1 | TAILLAMP LH                       |
| 1 | BOOT REAR                         |
| 1 | BOOT WEATHERSTRIP                 |
| 1 | BOOT BADGE 'RENAULT'              |
| 1 | BOOT BADGE                        |

|              | LIST     |                    |
|--------------|----------|--------------------|
| \$           | Bu       | 561.70 ✓           |
| \$           | na       | 411.90 ✓           |
| \$           | su       | 98.10 X            |
| \$           | su       | 80.80 X            |
| \$           | su       | 54.20 X            |
| \$           | cm       | 16.60 ✓            |
| \$           | su       | 82.10 X            |
| \$           | su       | 59.80 X            |
| \$           | Pl / Dir | 547.80 ✓           |
| \$           | R        | 114.50             |
| \$           | R        | 114.50             |
| \$           | R        | 745.80             |
| \$           | su       | 404.56             |
| \$           | su       | 401.40             |
| \$           | R        | 1,677.20           |
| \$           | su       | 178.20             |
| \$           | na       | 82.40              |
| \$           | na       | 95.80              |
| <b>TOTAL</b> |          | <b>\$ 5,727.36</b> |
| <b>10%</b>   |          | <b>\$ 572.74</b>   |
|              |          | <b>\$ 5,154.62</b> |

**Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP

|    |      |        |        |
|----|------|--------|--------|
| \$ | shca | 700.00 | 4000na |
| \$ | na   | 75.00  | ✓      |
| \$ | na   | 65.00  | X      |

AAD2009-024

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 754G

|                                  |           |    |                 |      |
|----------------------------------|-----------|----|-----------------|------|
|                                  | \$        | na | 50.00           | X    |
| 1SET BUMPER RETAINER LH CLIP RR  | \$        | na | 65.00           | X    |
| 1SET BUMPER BRACKET SIDE CLIP RR | \$        | na | 50.00           | X    |
| 1SET BUMPER RETAINER RH CLIP RR  | \$        | na | 69.00           | X    |
| 1SET BUMPER LOWER REAR RIVET     | \$        | na | 75.00           | ✓    |
| 1SET BUMPER LOWER REAR CLIP      | \$        | na | 80.00           | X    |
| 1 BOOT STICKER "Trans-cab"       | \$        | na | 80.00           | X    |
| 1 BOOT STICKER "6555-3333"       | \$        | na | 45.00           | X    |
| 1 TAILLAMP CLIP                  | \$        | na | 180.00          | 301a |
| 1 Rear Bumper Protector          | \$        | na | 60.00           | X    |
| 1 END PANEL TRIM CLIP            | \$        |    |                 |      |
| <b>TOTAL</b>                     | <b>\$</b> |    | <b>1,594.00</b> |      |
| <b>TOTAL PARTS</b>               | <b>\$</b> |    | <b>6,748.62</b> |      |

**LABOUR**

|   |           |    |                 |      |
|---|-----------|----|-----------------|------|
| To transfer of rear bumper fittings, attachment and perform water seepage test.   | \$        | na | 170.00          | X    |
| To Rust-Proofing and apply undercoat Of The Affected Areas.   | \$        | na | 250.00          | X    |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$        |    | 1,400.00        | 200l |
| To reinstall rear bumper parking sensor.  | \$        |    | 170.00          | 60l  |
| To Check Electrical Lighting Concerned.   | \$        |    | 170.00          | 15l  |
| Putty and spray painting of the affected portion.   | \$        |    | 1,400.00        | 220l |
| To transfer of rear end panel fittings, attachment and perform water seepage test   | \$        | na | 380.00          | X    |
| <b>TOTAL</b>  | <b>\$</b> |    | <b>3,940.00</b> |      |

KK Auto Consultants hence notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: