POLYMATH GARAGE PTE LTD

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE SINGAPORE 417868

TEL: 97253727

TO : MSIG DATE : 9/9/2020

: MOTOR INSURANCE CLAIM JOB TYPE: T/P CLAIM ATTENTION

ESTIMATE REPORT

VEHICLE DETAILS

: SMD4842K TO MSIA. VEHICLE NO

Xiao Chen. VEHICLE MODEL : HYUNDAI ELANTRA

CHASSIS NO : KMHD841CMJU727490

ACCIDENT DETAILS DATE

TIME

THIRD PARTY REQUESTOR / CONTACT NIGEL / 97253727

CLAIM DETAILS: PARTS

, ITĘMS	QTY	UNIT PRICE	TOTAL] .
1 REAR BUMPER De to-d	1	\$ 459.40	\$ 459.40	
2 REAR BUMPER SIDE HOLDER APP M	2	\$ 42.50	\$ 85.00	1+
3 REAR BUMPER REFLECTOR LH cult	1	\$ 127.60	\$ 127.60]/
4 REAR BUMPER LOWER GARNISH Delect	1	\$ 269.00	\$ 269.00	
5 REAR BUMPER REINFORCEMENT Mem	1	\$ 328.00	\$ 328.00	1
6 REAR BUMPER REINFORCEMENT LOWER BRACKET LH CMLC	1	\$ 18.00	\$ 18.00	
7 TAILLAMP LH Coulced.	1	\$ 362.30	\$ 362.30] ~

|200.30 LESS 20%

TOTAL PRICE:

1,649.30 329.86

96024

SUB TOTAL PRICE:

\$ 1,319.44

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL		
1	REAR BUMPER CLIPS No.	1 SET	\$ 50.00	\$	50.00	-30
2	REAR BUMPER TOP MOULDING WW	1	\$ 150.00	\$	-150.00	-80
3	REVERSE SENSOR NH MV	1 SET	\$ 280.00	\$	280.00	X.
	G(1)		TOTAL:	\$	480.00	

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	250	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 400.00	- 203	
3	WIRING CHECK	\$ 50.00	- 30	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	- 50	

TOTAL: \$ 950.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 1,799.44

TOTAL LABOUR COST: \$ 950.00

TOTAL REPAIR COST: \$ 2,749.44

APPROVED DETAILS

SURVEYOR:

totel: (600.2% L/S: 1250 1300 02 Days. FAX: CONTACT:

PART BY PART / LUMP SUM: NO. OF DAYS:

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: