

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2307K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER FOR BUMPER PRIMED (SN)	DEFORMED	1,158.63	1,158.63
1	1SET SENSOR BRACKETS PRI (SN)	NECESSARY	21.89	21.89
1	SENSOR BRACKET (SN)	NECESSARY	14.21	14.21
2	SENSOR BRACKET (SN)	NECESSARY	28.42	28.42
1	SENSOR BRACKET (SN)	NECESSARY	14.21	14.21
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	75.94	75.94
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	59.40	59.40
1	SUPPORT PART BUMPER INNER BRACKET RH (SN)	SERVICEABLE	54.69	-
1	GUIDE PIECE BUMPER SIDE BRACKET RH (SN)	CRACKED	20.91	20.91
1	HEADLAMPS FOR CURVE LIGHT (SN)	CRACKED	2,091.76	2,091.76
1	POWER MODULE FOR CORNERIN (SN)	SERVICEABLE	507.12	-
1	POWER MODULE FOR DAY DRIV (SN)	SHORTED	392.42	392.42
1	BALLAST FOR GAS DISCHARGE (SN)	SERVICEABLE	791.96	-
1	FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING (SN)	CRACKED	18.43	18.43
1	FENDER RH (SN)	BUCKLED	615.49	615.49
1	CROSS SUPPORT FENDER BRACKET RH (SN)	BENT	31.68	31.68
1	CROSS SUPPORT FENDER BRACKET UPPER (FRT) (SN)	BENT	20.73	20.73
4	RIVETTED CAP NUT (SN)	NECESSARY	8.92	8.92
1	WHEELHOUSE LINER FENDER LINER UPPER RH (SN)	DEFORMED	171.46	171.46
			6,098.27	4,744.50
	<u>LABOUR</u>			
	CHECK SHORT CIRCUIT / HARNESS REPAIR.		280.00	280.00
	DIAGNOSTIC AND PROGRAMMING.		480.00	480.00
	LABOUR.		4,200.00	1,680.00
	SPRAY PAINT.		3,200.00	3,200.00
			8,160.00	5,640.00
	GRAND TOTAL		14,258.27	10,384.50

RECOMMENDED COST OF REPAIRS			10,384.50
-----------------------------	--	--	-----------

Report Ref No. CS/GAI20009620/R1yf3e2





Report Ref No. CS/GAI20009620/R1yf3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.