

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2020		10 Sep 2020 10:13 Edit Adj Rpt	S\$4,700.00 Edit Estimates	S\$4,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	9 KOI MARKETING PTE LTD, Co. Reg. No.: 199903942H								
Main Claimant:	TRANS-CAB SERVICES PTE LTD								
Vehicle Reg. No.:	SHC5566R	Date of Loss:	05/09/2020 11:00 - :59 [71 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2004449	Policy/Cover Note No.:	MK000626 (Comprehensive) Coverage: 29/07/2020 - 28/07/2021						
Vehicle Reg. No. (Insured):	GBJ9960T	Policy No. (Claimant):							
		Excess:	S\$3,000.00						
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/09/2020]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC5566R (M2004449)**
[GBJ9960T]
TP
TRANS-CAB SERVICES PTE LTD
Sep 5 2020 11:00AM
[9 KOI MARKETING PTE LTD]
Trans-cab Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/20 10:20	General View	 Load JPG	☒
2	14/09/20 10:20	General View	 Load JPG	☒
3	14/09/20 10:20	General View	 Load JPG	☒
4	14/09/20 10:20	General View	 Load JPG	☒
5	14/09/20 10:21	General View	 Load JPG	☒
6	14/09/20 10:21	General View	 Load JPG	☒
7	14/09/20 10:21	General View	 Load JPG	☒
8	14/09/20 10:21	General View	 Load JPG	☒
9	14/09/20 10:21	General View	 Load JPG	☒
10	14/09/20 10:21	Odometer Reading	 Load JPG	☒
11	14/09/20 10:21	Chassis Number	 Load JPG	☒
12	14/09/20 10:21	General View	 Load JPG	☒
13	14/09/20 10:21	General View	 Load JPG	☒
14	14/09/20 10:21	General View	 Load JPG	☒
15	14/09/20 10:21	General View	 Load JPG	☒
16	14/09/20 10:21	General View	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	10/09/20 10:05	SHC5566 GIA INCOMPLETE	 Load PDF	
2	10/09/20 10:05	EST	 Load PDF	
3	10/09/20 10:05	PRILI ADVICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI20009622/KQF3S2**Date:** 15/09/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000626
Claimant Vehicle No :	SHC5566R	Insured Vehicle No :	GBJ9960T
Date of Loss:	05/09/2020	Nature of Claim:	TP
		Claim No:	M2004449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5566R		
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Engine No:	M9R8839C001966
Reg. Date:	15/09/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC279249
Colour:	Metallic White/Red	Odometer:	468918 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,221.30	4,377.36	15,843.94	78.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,340.00	1,520.00	4,820.00	76.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,561.30	5,897.36	20,663.94	77.80
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	26,561.30	4,700.00	21,861.30	82.31
+ GST 7.00/7.00% (S\$)	1,859.29	329.00	1,530.29	82.31
Nett Amount (S\$)	28,420.59	5,029.00	23,391.59	82.31

INSPECTION

Date of Assignment:	10/09/2020	
Date Inspected:	08/09/2020	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Sep 2020)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5566R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented/Distorted	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	-	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
6	1		*BUMPER REFLECTOR RH	Missing	16.60 FL	-	*16.60 FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
8	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	-	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
10	1		*BUMPER BEAM BRACKET RH REAR	Bent	114.50 FL	-	*114.50 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	-	*- FL
12	1		*BOOT REAR	Bent	1,677.20 FL	-	*1,677.20 FL
13	1		*BOOT FINISHER	Serviceable	344.70 FL	-	*- FL
14	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	-	*277.70 FL
15	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	-	*- FL
16	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	-	*82.40 FL
17	1		*BOOT BADGE	Necessary	95.80 FL	-	*95.80 FL
18	1		*BOOT STRUT	Serviceable	145.10 FL	-	*- FL
19	1		*BOOT HINGE LH	Repair	254.20 FL	-	*- FL
20	1		*BOOT HINGE RH	Repair	254.20 FL	-	*- FL
21	1		*BOOT LOCK	Repair	246.60 FL	-	*- FL
22	1		*BOOT SWITCH	Serviceable	113.00 FL	-	*- FL
23	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	-	*- FL
24	1		*TAILLAMP RH	Serviceable	401.40 FL	-	*- FL
25	1		*TAILLAMP LH	Serviceable	401.40 FL	-	*- FL
26	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	-	*745.80 FL
27	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	-	*- FL
28	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	-	*- FL
29	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	-	*- FL
30	1		*EXHAUST REAR	Repair	5,263.60 FL	-	*- FL
31	1		*EXHAUST CAP REAR	Repair	125.40 FL	-	*- FL
32	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	-	*- FL
33	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	-	*- FL
34	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	-	*- FL
35	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
36	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	-	*75.00 FS
37	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	60.00 FS	-	*- FS
38	1		*SET BUMPER BRACKET SIDE CLIP RR	Not Necessary	70.00 FS	-	*- FS
39	1		*SET BUMPER RETAINER CLIP RR	Not Necessary	65.00 FS	-	*- FS
40	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	70.00 FS	-	*- FS
41	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	-	*75.00 FS
42	2		*SEAM SEALANT	Not Necessary	190.00 FS	-	*- FS
43	1		*SET BOOT FINISHER CLIP	Not Necessary	55.00 FS	-	*- FS
44	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
45	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
46	1		*RENAULT TYRE RIM (ROUE 7J 16H)	Serviceable	385.00 FS	-	*- FS
47	1		*RENAULT TYRE 215/60/16	Serviceable	330.00 FS	-	*- FS
48	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	-	*- FS
49	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	-	*- FS
50	1		*SET REAR LICENCE PLATE WITH HOLDER	Not Necessary	140.00 FS	-	*- FS
51	1		*SET FENDER PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	-	*- FS
52	1		*SET WHEELARCH RR CLIP	Not Necessary	65.00 FS	-	*- FS
53	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- FS
54	2		*REAR WINDSCREEN SEALANT	Not Necessary	150.00 FS	-	*- FS
55	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	-	*- FS
56	1		*EXHAUST MOUNTING	Serviceable	65.00 FS	-	*- FS
57	1		*EXHAUST BRACKET REAR	Repair	55.00 FS	-	*- FS
58	1		*BOOT WEATHERSTRIP (50%)	Cut	160.38 FS	-	*89.10 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,080.29	4,830.50
- List Item Discount on L Items 10.00/10.00% (\$)	1,858.99	453.14
Total Parts (\$)	20,221.30	4,377.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
2	TO REMOVE AND REFIT BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
3	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
4	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	600.00
5	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	60.00
6	TO REMOVE AND REFIT REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
8	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
9	TO REMOVE AND REFIT REAR FENDER PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	660.00
11	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
12	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
13	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
16	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (\$\$)			6,340.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >