

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL 6481 7773 / 6481 1403 FAX 6484 4978

E-mail tsac303@singnet.com.sg

M / s : **First Capital Insurance Ltd**
36, Robinson Road, #16-01
City House, Singapore 068877

Estimate bill : TT 35 / 20 / TP / WT

Registration No : GBJ1255Z

Make / model : Toyota Dyna 150

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Not Authorised

Repair After Paint

2 days

Mileage :

Date : 08 / 09 / 2020

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SH7149S AND GBJ1255Z ALONG CAIRNHILL ROAD ON 26 AUGUST 2020 AT 1335 HRS.

lpc	RH door	\$	<i>12</i>	1,649.00	<i>X</i>
	Sub total :	\$		1,649.00	
	Less 10% discount:	\$		164.90	
	A total :	\$		1,484.10	
	Remove & refit RH door.	}	\$	400.00	<i>1500</i>
	Heat / weld / beating / pull / straighten / align front chassis frame by Chassis Alignment Jack.				
	Tuff kote front damaged portion.	\$	<i>22</i>	150.00	<i>X</i>
	Putty / primer application, spray painting RH door.	\$		400.00	<i>2000</i>
	Grand final amount:	\$		2,434.10	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

