

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

No. : 06221

Date : 02-Sep-2020

PAGE : 1

Vehicle Insured : SMD2861J
Accident Date : 31-Aug-2020

Our Ref : 020101 (AIG) / CHAN

HUI SHOON CAR RENTAL
BLK 1 SIN MING IND. EST. SECTOR C
#01-125
Singapore 575636

Not Authorised
L1 Imp &
Repair After Paint
3 days

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS 1.6 SGH1597M

- | | | | | |
|------|--------------------------------|-----|--------|---|
| 1 pc | Front bumper fascia | Ry | 344.40 | ✓ |
| 1 pc | Front o/s bumper side retainer | D.I | 41.70 | ✓ |
| 1 pc | Front bumper reinforcement | | 339.70 | ? |
| 1 pc | Front o/s bumper foglamp | Scr | 224.20 | ✓ |
| 1 pc | Front w/s glass washer tank | Sn | 49.50 | X |
| 1 pc | O/s headlamp | Cr | 331.70 | ✓ |
| 1 pc | Front o/s fender | R | 375.10 | X |
| 1 pc | Front o/s fender inner shield | Sn | 182.40 | X |

1,888.70

Less 25% : 472.18

1,416.52

To rewire damaged parts and refocus headlamp beam.

20l
30.00

To putty and spray replaced parts

400l
550.00

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

300l
450.00

Total : S\$ 2,446.52

Singapore Dollars Two Thousand Four Hundred and Forty Six and Cents Fifty Two Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: