



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007086
INV Date 19/10/2020
Reference CC4/LPC20009625/Epa3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SGG 239J
Insured Veh. SJQ 6863D
Claim No. 20/20/20/VP05/023584
Policy No. Z20VP05026806
Accident Date 25/08/2020
Inspection Date 11/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20009625/Epa3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 19-10-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJQ 6863D	Veh. Inspected	SGG 239J
Policy No.	Z20VP05026806	Coverage (\$)	0.00
Claim No.	20/20/20/VP05/023584	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	08/09/2020

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN TOURAN	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WVGZZZ1TZJW108563	Colour	WHITE
Odometer	40572	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	GOODYEAR	5 mm
L/H Front Tyre	205/55 R16	GOODYEAR	5 mm
R/H Rear Tyre	205/55 R16	GOODYEAR	5 mm
L/H Rear Tyre	205/55 R16	GOODYEAR	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/08/2020	Inspection Date	11/09/2020
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 239J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED (SN)	DENTED	1,231.02	1,231.02
1	BUMPER (BUMPER REINFORCEMENT)(SN)	NOT NECESSARY	508.63	-
1	ATTACHMENT STRIP (SN)	NOT NECESSARY	60.62	-
1	GUIDE PIECE (REAR BUMPER LH GUIDE)(SN)	NOT NECESSARY	39.36	-
1	GUIDE PIECE (REAR BUMPER RH GUIDE)(SN)	NOT NECESSARY	39.36	-
1	GUIDE PIECE (BUMPER BRACKET LH)(SN)	NOT NECESSARY	32.03	-
1	GUIDE PIECE (BUMPER BRACKET RH)(SN)	NOT NECESSARY	32.03	-
1	SPOILER SATIN BLACK (SN)	CUT	319.10	319.10
	REVERSE SENSORS (SN)	NOT NECESSARY	400.00	-
			2,662.15	1,550.12
	<u>LABOUR</u>			
	SPRAY PAINTING.		2,400.00	800.00
	LABOUR.		2,520.00	840.00
	DIAGNOSTIC AND PROGRAMMING.		480.00	480.00
	CHECK SHORT CIRCUIT/HARNESS REPAIR.	NOT NECESSARY	280.00	-
			5,680.00	2,120.00
GRAND TOTAL			8,342.15	3,670.12
RECOMMENDED COST OF REPAIRS				3,670.12

Report Ref No. CC4/LPC20009625/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGG 239J

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGG 239J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

