

ASS. REC. BY:

REF:

Special Instruction:

Surveyor: Ram

Jenny Pe

ASSIGNMENT (Office)

08/09/2020

From (Person):

of

INC

Date/Time:

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 5186P

Insured:

YN 5036U

at Workshop in/s

Kum Chew Motor Workshop

Tel:

6453 6256

of

160 Sin Ming Drive #05-08

Policy No:

Claim No:

MT/1059662-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10 21am @ 26/8/19

Person Contacted:

mdm-him

Vehicle:

IN/OUT

Date/Time

Action/Instruction

Vehicle X

YN 5036U NBR/1-EP180/9823/1

D.O.A. 26/08/2019

SLK 5186P X

Disassemble: 30/8/2019

After repair: 10/9/2019

REF: INC

PES

ASSIGNMENT

From: Date: 28/8/19

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 5186P

at Workshop m/s Kumchew

of 160 Sin Ming Drive #05-08

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLK 5186P Yr Regn: MAR / 2011

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: Volkswagen Touran cc 1340

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 129858 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WUP221T2BWO53T65

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16 michelin

R: 205/55 R16 crucero

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 1 mm

L/Bal. 5 mm L/Bal. 1 mm

D.O.A. 26/08/2019

D.O.I. 28/08/2019 2:40pm

Survey held at Kumchew

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
Range: \$3000 - \$4000
Repair day: 4 days

15/09/20 Submit LS \$6300, 6 days (Red \$1800, 22%)

MV: \$21000
PV: \$17803
NV: \$3000

ENTERED 12 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report

1) 15/09 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Video

50

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Wheel end (\$)

Report Format: ~~PES~~ TP

Lump Sum: 6300