

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 48445

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0644/2020/NS
Date : 8-Sep-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Edy Susanto Panggabean
Address : 80 Jellicoe Road
#22-01
Singapore 208766
Telephone : HP +65 96323767
Type of Claim : Own Damage Claims
Policy No. : 1800062546-02
Vehicle No : **SKF 2517 B**
Model Code : Audi A6 1.8 TFSI S TRONIC
Model / Year : 6/6/2018
Engine No : CYG 023009
Chassis No : WAUZZZ4G6JN034633
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Sep-20
Place of Accident : Between Stamford And Bencoolen Rd

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

TELEFAX

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 2517 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N	\$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 400.00 ✓	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,800.00 1000 ✓	✓
4	TO RESPRAY FRONT BUMPER AND BONNET.		\$ 2,500.00 1100 ✓	✓
5	TO CARRY OUT CALIBRATION FOR FRONT SOFTWARE FOR DISTANCE REGULATION AND RADAR SENSOR.	S/N	\$ 280.00 ✓	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u>\$ 5,652.00</u>	

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2517 B

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
1	FRONT BUMPER <i>Disto fcd</i>	S 3,021.00	✓ <i>2416</i>
2	FRONT BUMPER ATTACHMENT PARTS <i>the new</i>	S 537.00	✗
3	FRONT BUMPER TOWING EYE COVER <i>De fcd</i>	S 46.00	✓
4	FRONT BUMPER SECURING STRIP <i>the new</i>	2 S 14.00	✗
5	FRONT BUMPER GRILLE - LOWER CENTRE <i>the new</i>	S 126.00	+
6	FRONT BUMPER LOCKING CLIP <i>the new</i>	14 S 52.00	✗
7	FRONT BUMPER ADAPTER - RH <i>the new</i>	S 37.00	✗
8	FRONT BUMPER CLOSING ELEMENT <i>the new torn</i>	S 216.00	✗ <i>172.80</i>
9	FRONT BUMPER SPOILER <i>} Not the new</i>	S 246.00	+
10	FRONT BUMPER SPOILER	S 935.00	+
11	RADIATOR GRILLE <i>crushed</i>	S 1,912.00	✓ <i>1529.60</i>
12	RADIATOR GRILLE COVER <i>the new</i>	S 36.00	?
13	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT <i>the new</i>	2 S 132.00	✓ <i>104.32</i>
14	FRONT PARKING AID SENSOR - INNER / OUTER <i>the new</i>	2 TBC	+
15	SIGNAL HORN - RH HIGH TONE <i>the new</i>	S 232.00	?
16	SPRING SHACKLE - RH <i>the new</i>	S 47.00	?
17	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>Bent.</i>	S 816.00	? <i>652.80</i>
18	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	S 234.00	✓ <i>187.20</i>
19	FOAM FILLER PIECE COVER <i>the new</i>	S 121.00	?
20	FRONT BUMPER BRACKET HOLDER - RH <i>the new</i>	S 257.00	?
SUB TOTAL SPARE PARTS		:	<u>\$ 9,017.00</u>

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2517 B

S/N	PARTS DESCRIPTION		DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT BUMPER BRACE - RH <i>Not rec</i>	\$	30.00	? <i>X</i>
22	CAUTION SIGN STICKER <i>Not rec</i>	NEC \$	14.00	? <i>X</i>
23	TEMPERATURE SENSOR BRACKET <i>Not rec</i>	\$	23.00	? <i>X</i>
24	HEADLIGHT MOUNTING - RH <i>Cracked</i>	\$	117.00	? <i>93.60</i>
25	LED HEADLIGHT - RH <i>Cracked</i>	\$	9,337.00	✓ <i>7469.60</i>
26	LIFT CYLINDER - RH <i>Cracked</i>	\$	234.00	? ✓ <i>186.80</i>
27	LIFT CYLINDER HOSE <i>Not rec</i>	\$	472.00	<i>X</i>
28	LOCK CARRIER <i>Not rec</i>	\$	1,234.00	<i>X</i>
29	READY MIX COOLANT <i>Not rec</i>	\$	91.00	<i>X</i>
30	RADIATOR AIR GUIDE - RH <i>Not rec</i>	\$	28.00	? <i>X</i>
31	RADIATOR AIR GUIDE COVER - UPPER CENTRE <i>Not rec</i>		29.00	? <i>X</i>
32	RADIATOR AIR GUIDE SEALING STRIP <i>Not rec</i>	\$	23.00	? <i>X</i>
33	FRONT BUMPER AIR GUIDE GRILLE - RH	\$	566.00	✓ <i>452.40</i>
34	FRONT BUMPER AIR GUIDE GRILLE COVER - RH <i>Missing</i>	\$	51.00	✓ <i>40.32</i>
35	FRONT WHEEL SPOILER - RH <i>Not rec</i>	\$	261.00	<i>X</i>
36	HEADLIGHT COVER CAP - RH <i>Not rec</i>	\$	57.00	<i>X</i>
37	DISTANCE REGULATION CONTROL UNIT - RH <i>Not rec</i>	\$	6,609.00	? <i>X</i>
38	RADAR SENSOR COVER FRAME - RH <i>Not rec</i>	\$	13.00	? <i>X</i>
39	BONNET <i>Backend (Aluminium)</i>	\$	5,374.00	✓ <i>4299.20</i>
40	FRONT NO PLATE <i>Dented</i>	S/N \$	60.00	✓
41	SUNDRIES <i>Not rec</i>	\$	250.00	? <i>208.40</i>
TOTAL SPARE PARTS		:	\$ 33,890.00	
TOTAL LABOUR CHARGES		:	\$ 5,052.00	
GRAND TOTAL		:	\$ 38,942.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2517 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Disto f-d</i>	\$ 3,021.00	✓
2	FRONT BUMPER ATTACHMENT PARTS	\$ 537.00	?
3	FRONT BUMPER TOWING EYE COVER <i>Del d</i>	\$ 46.00	✓
4	FRONT BUMPER SECURING STRIP	2 \$ 14.00	?
5	FRONT BUMPER GRILLE - LOWER CENTRE <i>new in</i>	\$ 126.00	+
6	FRONT BUMPER LOCKING CLIP	14 \$ 52.00	?
7	FRONT BUMPER ADAPTER - RH	\$ 37.00	?
8	FRONT BUMPER CLOSING ELEMENT <i>new in / PR</i>	\$ 216.00	+
9	FRONT BUMPER SPOILER	\$ 246.00	+
10	FRONT BUMPER SPOILER <i>} Not New</i>	\$ 935.00	+
11	RADIATOR GRILLE <i>cracked</i>	\$ 1,912.00	✓
12	RADIATOR GRILLE COVER <i>Not ?</i>	\$ 36.00	?
13	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT <i>Not New</i>	2 \$ 132.00	✓
14	FRONT PARKING AID SENSOR - INNER / OUTER <i>Not in</i>	2	TBC
15	SIGNAL HORN - RH HIGH TONE	\$ 232.00	?
16	SPRING SHACKLE - RH	\$ 47.00	?
17	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>✓ M</i>	\$ 816.00	?
18	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	\$ 234.00	✓
19	FOAM FILLER PIECE COVER	\$ 121.00	?
20	FRONT BUMPER BRACKET HOLDER - RH	\$ 257.00	?

SUB TOTAL SPARE PARTS

: \$ 9,017.00

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2517 B

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21	FRONT BUMPER BRACE - RH ?	S	30.00 ?
22	CAUTION SIGN STICKER ?	NEC S	14.00 ?
23	TEMPERATURE SENSOR BRACKET ?	S	23.00 ?
24	HEADLIGHT MOUNTING - RH ? <i>OR</i>	S	117.00 ?
25	LED HEADLIGHT - RH <i>Cracked</i>	S	9,337.00 ✓
26	LIFT CYLINDER - RH ?	S	234.00 ?
27	LIFT CYLINDER HOSE <i>new</i>	S	472.00 ✓
28	LOCK CARRIER <i>new</i>	S	1,234.00 X
29	READY MIX COOLANT <i>new</i>	S	91.00 X
30	RADIATOR AIR GUIDE - RH ?	S	28.00 ?
31	RADIATOR AIR GUIDE COVER - UPPER CENTRE ?	S	29.00 ?
32	RADIATOR AIR GUIDE SEALING STRIP ?	S	23.00 ?
33	FRONT BUMPER AIR GUIDE GRILLE - RH	S	566.00 ✓
34	FRONT BUMPER AIR GUIDE GRILLE COVER - RH <i>Missing</i>	S	51.00 ✓
35	FRONT WHEEL SPOILER - RH <i>new</i>	S	261.00 X
36	HEADLIGHT COVER CAP - RH <i>new</i>	S	57.00 X
37	DISTANCE REGULATION CONTROL UNIT - RH ?	S	6,609.00 ?
38	RADAR SENSOR COVER FRAME - RH ?	S	13.00 ?
39	BONNET <i>Buckled (Aluminium)</i>	S	5,374.00 ✓
40	FRONT NO PLATE <i>Dented</i>	S/N S	60.00 ✓
41	SUNDRIES ?	S	250.00 ?

TOTAL SPARE PARTS	:	\$ 33,890.00
TOTAL LABOUR CHARGES	:	\$ 5,052.00
GRAND TOTAL	:	<u>\$ 38,942.00</u>

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

8 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0644/2020/NS

Date

22-Sep-20

Service Advisor

Glory Tan

Pages

1 OF 1

Regn No

SKF 2517 B

Model No

Audi A6 1.8 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
Parts			
1	Bonnet striker RHS ✓ DT	\$ 49.00	39.20
2	Bonnet lid lock ✓ DT/jammed	\$ 212.00	169.20
TOTAL		\$ 261.00	

For Premium Automobiles Pte Ltd

Steve
22/9/20, 1.30pm

Authorised Signature



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



WIP : 48445

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0644/2020/NS
Date	:	8-Sep-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

7 days - ok - Jy - 24 Oct 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Edy Susanto Panggabean
Address	:	80 Jellicoe Road #22-01 Singapore 208766
Telephone	:	HP +65 96323767
Type of Claim	:	Own Damage Claims
Policy No.	:	1800062546-02
Vehicle No	:	SKF 2517 B
Model Code	:	Audi A6 1.8 TFSI S TRONIC
Model / Year	:	6/6/2018
Engine No	:	CYG 023009
Chassis No	:	WAUZZZ4G6JN034633
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Sep-20
Place of Accident	:	Between Stamford And Bencoolen Rd



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 2517 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N	\$ 480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 400.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,800.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET.		\$ 2,500.00	\$	1,100.00
5	TO CARRY OUT CALIBRATION FOR FRONT SOFTWARE FOR DISTANCE REGULATION AND RADAR SENSOR.	S/N	\$ 280.00	\$	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,652.00	\$	3,302.00



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2517 B

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 3,021.00	\$ 2,416.80
2	FRONT BUMPER ATTACHMENT PARTS	\$ 537.00	
3	FRONT BUMPER TOWING EYE COVER	\$ 46.00	
4	FRONT BUMPER SECURING STRIP	2 \$ 14.00	
5	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 126.00	
6	FRONT BUMPER LOCKING CLIP	14 \$ 52.00	
7	FRONT BUMPER ADAPTER - RH	\$ 37.00	
8	FRONT BUMPER CLOSING ELEMENT	\$ 216.00	\$ 172.80
9	FRONT BUMPER SPOILER	\$ 246.00	
10	FRONT BUMPER SPOILER	\$ 935.00	
11	RADIATOR GRILLE	\$ 1,912.00	\$ 1,529.60
12	RADIATOR GRILLE COVER	\$ 36.00	
13	RADIATOR GRILLE SENSOR SUPPORT - LH / RH FRONT	2 \$ 132.00	\$ 104.32
14	FRONT PARKING AID SENSOR - INNER / OUTER	2 TBC	
15	SIGNAL HORN - RH HIGH TONE	\$ 232.00	
16	SPRING SHACKLE - RH	\$ 47.00	
17	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 816.00	\$ 652.80
18	FRONT BUMPER FOAM FILLER PIECE	\$ 234.00	\$ 187.20
19	FOAM FILLER PIECE COVER	\$ 121.00	
20	FRONT BUMPER BRACKET HOLDER - RH	\$ 257.00	
SUB TOTAL SPARE PARTS		\$ 9,017.00	\$ 5,063.52

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 2517 B

S/N	PARTS DESCRIPTION		<u>DAMAGED PARTS & PRICES</u>		REMARKS
			S/NETT		
		c/f		\$	5,063.52
21	FRONT BUMPER BRACE - RH		\$ 30.00		
22	CAUTION SIGN STICKER	NEC	\$ 14.00		
23	TEMPERATURE SENSOR BRACKET		\$ 23.00		
24	HEADLIGHT MOUNTING - RH		\$ 117.00	\$ 93.60	
25	LED HEADLIGHT - RH		\$ 9,337.00	\$ 7,469.60	
26	LIFT CYLINDER - RH		\$ 234.00	\$ 186.80	
27	LIFT CYLINDER HOSE		\$ 472.00		
28	LOCK CARRIER		\$ 1,234.00		
29	READY MIX COOLANT		\$ 91.00		
30	RADIATOR AIR GUIDE - RH		\$ 28.00		
31	RADIATOR AIR GUIDE COVER - UPPER CENTRE		\$ 29.00		
32	RADIATOR AIR GUIDE SEALING STRIP		\$ 23.00		
33	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 566.00	\$ 452.40	
34	FRONT BUMPER AIR GUIDE GRILLE COVER - RH		\$ 51.00	\$ 40.32	
35	FRONT WHEEL SPOILER - RH		\$ 261.00		
36	HEADLIGHT COVER CAP - RH		\$ 57.00		
37	DISTANCE REGULATION CONTROL UNIT - RH		\$ 6,609.00		
38	RADAR SENSOR COVER FRAME - RH		\$ 13.00		
39	BONNET		\$ 5,374.00	\$ 4,299.20	
40	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00	
41	SUPPLERMENTARY		\$ 261.00	\$ 208.40	
42	SUNDRIES		\$ 250.00		
TOTAL SPARE PARTS			\$ 34,151.00	\$ 17,873.84	
TOTAL LABOUR CHARGES			\$ 5,652.00	\$ 3,302.00	
GRAND TOTAL			\$ 39,803.00	\$ 21,175.84	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0644/2020/NS 22-Sep-20 Glory Tan 1 OF 1 SKF 2517 B Audi A6 1.8 TFSI S TRONIC	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Bonnet striker RHS	\$ 49.00	\$	39.20
2	Bonnet lid lock	\$ 212.00	\$	169.20
TOTAL		\$ 261.00	\$	208.40

For Premium Automobiles Pte Ltd

 Authorised Signature



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

View Received Message

This mail is associated with :

***SKF2517B (1342674426SG)**

OD

Sep 8 2020 11:00AM

[EDY SUSANTO PANGGABEAN]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 10/09/2020 17:18 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$24185.00) - SKF2517B - Claim Handler: Abu Kassim, Noor Mariesa

Approved:24185.00:Authorise repair, labour 2 at \$250. B/f paint required. Re-inspection to be done for damage check and supplementary items / labour with clear photos.

DOCUMENTS SUMMARY

There are no documents.

Print Received Message

No 2ND 1A??

This mail is associated with :

*SKF2517B (1342674426SG)

OD

Sep 8 2020 11:00AM

[EDY SUSANTO PANGGABEAN]

Premium Automobiles Pte Ltd

None

From **AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG)**, sent on 10/09/2020 17:18 PM.
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$24185.00) - SKF2517B - Claim Handler: Abu Kassim, Noor Mariesa**

Approved:24185.00:Authorise repair. labour 2 at \$250. B/f paint required. Re-inspection to be done for damage check and supplementary items / labour with clear photos.

Headup
Replacement.

* Labour No. 2 adjust to 6 hrs. Admin will settle it with WSP.

Repair days

7 days.

64572625
- - -