

ESTIMATE BILL

Date 8 Sep 2020

To

Owner Tay Hui Fong

Vehicle Reg No SFJ6922B

Make/Model Toyota Alphard 2.5 SC CVT

Chassis No AGH300140585

Year Mfg 2017

Date of Accident 31 August 2020

LDK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE COST OF REPAIR TO "TOYOTA ALPHARD 2.5 SC CVT"

" REG. NO. SFJ6922B "

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
<u>List Price Items</u>			
1	Rear Bumper / Re		
10	Rear Bumper Clips / MC		
1	Rear Bumper Side Retainer - RH / At		
1	Rear Side Bumper - RH X		
1	Rear Side Bumper Reflector - RH X		
1	Rear Bumper Sponge X		
1	Rear Bumper Towing Cover - RH X		
1	Rear Bumper Center Garnish X		
1	Rear End Panel X		
1	Rear End Panel Top Garnish X		
	Rear Fender Lower Panel Repair X		
1	Rear Fender Garnish - RH / TN		
8	Rear Fender Garnish Clip / MC		
1	RHR Door Repair X		
1	RHR Door Rubber X		
15	RHR Door Rivet X		
1	RHR Door Outer Moulding X		
1	RHR Door Top Chrome X		
1	RHR Door Side Quarter Garnish Repair X		
2	Reverse Sensor X		
2	Parking Sensor X		
Less 25%			0.00
Total List Items			0.00
BALANCE B/F			0.00



(Panel Beating, Repair, Servicing & General Claims)
10, AMK Autopoint, #04-04 Ang Mo Kio, Ind. Park 2A, Singapore 568047
TEL: 6483 3353 FAX: 6484 2457 Email: ldemail@singnet.com.sg
Reg No: S2806993D

ESTIMATE BILL

Date: 8 Sep 2020

To:

Owner: Tay Hui Fong

Vehicle Reg No: SFJ6922B

Make/Model: Toyota Alphard 2.5 SC CVT

Chassis No: AGH300140585

Year Mfg: 2017

Date of Accident: 31 August 2020

ESTIMATE COST OF REPAIR TO "TOYOTA ALPHARD 2.5 SC CVT"			
" REG. NO. SFJ6922B"			
QTY	DESCRIPTION	UNIT PRICE	AMOUNT
	BALANCE C/F		
	<u>Labour Charges</u>		
	To replace, refocus, re-wire taillamp, brake lights, bumper beam & check wirings, re-set computer		180.00
	To remove, re-fix parking sensor and camera		80.00
	To panel beat, cut, weld, remove and replace the above parts		1,200.00
	To putty and re-spray paint of the affected areas		1,800.00
	Total Labour Charges		3,260.00
	ESTIMATE PARTS AND LABOUR GRAND TOTAL \$		

X 1W
40.
400.
750.

5 Days.

Unp. sm. repair.

After repair photos.

Gino Rianp - 82880282

9/9/2020.