



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2006538
INV Date 22/09/2020
Reference CS/AGI20009633/Atf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SMU 121U

Insured Veh. SBT 1001L

Claim No. C10007231

Policy No.

Accident Date 07/09/2020

Inspection Date 09/09/2020

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI20009633/Atf3n2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 22-09-2020		
Code : AGI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBT 1001L	Veh. Inspected	SMU 121U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007231	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	08/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A5 CABRIOLET	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8F4AN008422	Colour	BLACK	
Odometer	134539	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	MICHELIN	6 mm	
L/H Front Tyre	225/50 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/50 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/50 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/09/2020	Inspection Date	09/09/2020	
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 121U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH	DENTED	1,062.00	1,062.00
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	179.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	3,484.00	-
1	FRONT DOOR WING MIRROR LH	NOT NECESSARY	1,325.00	-
1	FRONT DOOR WING MIRROR COVER LH	TO REPAIR SEE LABOUR	565.00	-
1	FRONT WHEEL RIM LH	NOT NECESSARY	746.00	-
	LESS 5% DISCOUNT		-368.05	-53.10
			6,992.95	1,008.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT FENDER INNER SHIELD CLIPS LH (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING,REMOVE AND REFIT PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND FRONT DOOR WING MIRROR COVER LH.		800.00	500.00
	SPRAY PAINTING TO AFFECTED AREA.		800.00	600.00
	WIRING CHECK.		50.00	30.00
	TUFF COAT.		150.00	50.00
	TO TRANSFER FRONT DOOR FITTINGS.	NOT NECESSARY	150.00	-
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
			2,100.00	1,180.00
	GRAND TOTAL		9,142.95	2,188.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CS/AGI20009633/Atf3n2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 121U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

