AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT SINGAPORE 417883 TEL: 65096584

TO : BUDGET DIRECT DATE : 9/9/2020

ATTENTION : MOTOR INSURANCE CLAIM JOB TYPE : T/P CLAIM

ESTIMATE REPORT

VEHICLE DETAILS

VEHICLE NO : SMU121U

VEHICLE MODEL : AUDI AS CABRIOLET

CHASSIS NO : WAUZZZ8F4AN008422

ACCIDENT DETAILS DATE :

TIME :

THIRD PARTY REQUESTOR / CONTACT : SIONG / 97864483

CLAIM DETAILS: PARTS

CLA	ITEMS	QTY		UNIT PRICE		TOTAL
		1	5	1.062.00	\$	1,062.00
4	FRONT FENDER LH Dended	+	7	179.00	5	179.00
2	FRONT FENDER INNER SHIELD LH	1	7		,	3,484.00
3	FRONT DOOR LH	1	\$	3,484.00	<u> </u>	
	FRONT DOOR WING MIRROR LH	1	\$	1,325.00	\$	1,325.00
	FRONT DOOR WING MIRROR COVER LH	1	\$	565.00	\$	565.00
		1	5	746.00	\$	746.00
6	FRONT WHEEL RIM LH	TOTAL PRICE:	<u> </u>		\$	7.361.00
		IOIAL FRICE.			~	.,

TOTAL PRICE: \$ 7,361.00

1062 LESS 5% \$ 368.05

SUB TOTAL PRICE: \$ 6,992.95

1008.90 SUB TOTAL PRI

Dense

SPECIAL NETT ITEMS

SFEC	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT FENDER INNER SHIELD CLIPS LH	1 SET	\$ 50.00	\$ 50.00
			TOTAL:	\$ 50.00

LABOUR

LABOUR							
	JOB		PRICE	ADJUSTED COST	APPROVED		
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$	800.00	500			
2	SPRAY PAINTING TO AFFECTED AREA	\$	-800.00	- 600.			
3	WIRING CHECK	\$	50.00	- 30			
4	TUFF COAT	\$	150.00	- 50			
5	TO TRANSFER FRONT DOOR FITTINGS	\$	150.00	X			
6	TO PERFORM WHEEL ALIGNMENT	\$	150.00	X			

TOTAL: \$ 2,100.00

1180

ESTIMATE REPORT

total 2188.50 1/5: 1750 030ays \$ 7,042.95 **TOTAL PARTS COST:** \$ 2,100.00 TOTAL LABOUR COST: \$ 9,142.95 TOTAL REPAIR COST:

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM: NO. OF DAYS:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: