

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20009634/T1YF3E2
Date: 24/09/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	ML000245
Claimant Vehicle No : SHD7087M	Insured Vehicle No :	GBH3057B
Date of Loss: 07/09/2020	Nature of Claim:	TP Claim No: M2004405

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7087M	Engine No:	2ZRR959465
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU003536878
Reg. Date:	11/11/2016 (Man. Year: 2016)	Odometer:	687178 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,333.22	1,245.17	1,088.05	46.63
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,420.00	940.00	480.00	33.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,764.22	2,196.17	1,568.05	41.66
Approved Total (Overridden) (\$\$)		1,750.00		
(\$\$)	3,764.22	1,750.00	2,014.22	53.51
+ GST 7.00/7.00% (\$\$)	263.50	122.50	141.00	53.51
Nett Amount (\$\$)	4,027.72	1,872.50	2,155.22	53.51

INSPECTION

Date of Assignment:	09/09/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	08/09/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2020)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD7087M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Deformed	458.60 FL	-	*458.60 FL
2	1		*REAR BUMPER UNDER COVER	Deformed	552.60 FL	-	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 FL	-	*- FL
4	2		*REAR BUMPER REINFORCEMENT STAY ARM LH/RH	Not Necessary	279.20 FL	-	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	225.40 FL	-	*- FL
7	1		*REAR BUMPER TOW COVER	Not Necessary	82.70 FL	-	*- FL
8	1		*REAR BUMPER UNDER COVER CENTRE	Not Necessary	232.00 FL	-	*- FL
9	1		*SMART KEY ANTENNA SENSOR	Not Necessary	147.00 FL	-	*- FL
10	1		*REAR TRUNK LID PRIUS EMBLEM	Necessary	52.40 FL	-	*52.40 FL
11	1		*REAR TRUNK LID HYBRID EMBLEM	Necessary	52.90 FL	-	*52.90 FL
12	1		*REAR TRUNK LID TOTOTA EMBLEM	Necessary	60.80 FL	-	*60.80 FL
13	1		*REAR TRUNK LID APP STICKER	Necessary	40.00 FS	-	*40.00 FS
14	2		*REAR TRUNK LID COMFORT & TEL NO. STICKER	Necessary	120.00 FS	-	*120.00 FS
15	1		*REAR REVERSE SENSOR	Not Working	135.70 FS	-	*135.70 FS
16	1		*REAR BUMPER MAT	Necessary	50.00 FS	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,830.10	1,545.00
- List Item Discount on L Items 20.00/25.00% (\$\$)	496.88	299.83
Total Parts (\$\$)	2,333.22	1,245.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	680.00	480.00
2	SPRAY PAINTING	New	500.00	400.00
3	WIRING CHARGE	New	60.00	30.00
4	TUFF COATING	New	120.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			1,420.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >