



Not Notwork
U/Sing &
Resurvey After Paint
7 days

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

ISO TEAM ACCESS PTE LTD
 8 CHANGI NORTH STREET 1
 ISOTEAM BUILDING SINGAPORE 498829

Attention : THE OWNER
 Contact : 67470220 Fax No. : 67470110

Estimate : ES007027
 Date : 07/09/2020
 Vehicle Num. : GBD2653H
 Make/Model : TOYOTA HIACE-2014
 Chassis/Eng# : JTFHT02P800145783/1KD2424898
 Accident Date : 05/09/2020
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	TAIL GATE		
2.	1	REAR W/SCREEN MOULDING		
3.	1	REAR WIPER BLADE		
4.	1	REAR WIPER ARM		
5.	1	REAR WIPER MOTOR		
6.	1	REAR WINDSCREEN GLASS		
7.	1	TAIL GATE LOCK		
8.	1	TAIL GATE INNER BOARD		
9.	1	TAIL GATE OUTER GARNISH		
10.	2	REAR NUMBER PLATE LAMP		
11.	1	TAIL GATE OUTER HANDLE		
12.	1	TOYOTA LOGO		
13.	1	TOYOTA HIACE STICKER		
14.	1	TAIL LAMP R/H		
15.	1	TAIL LAMP LOWER PANEL R/H		
16.	1	REAR FENDER R/H		
17.	1	TAIL LAMP L/H		
18.	1	REAR BUMPER		
19.	1	REAR VIEW MIRROR		
20.	6	REAR BUMPER CLIP		
21.	2	REAR BUMPER BRACKET		
22.	1	REAR END PANEL OUTER		
23.	1	REAR END PANEL TOP PLATE		
24.	1	BOOT WEATHERSTRIP		
25.	1	SPARE TIRE CARRIAGE TOOL COVER		
26.	1	SPARE TIRE CARRIAGE		
				2,278.20
				138.70
				65.57
				98.57
				650.42
				1,440.00
				286.68
				193.64
				386.00
				143.00
				147.58
				68.59
				58.31
				311.86
				239.62
				1,470.66
				311.86
				425.30
				362.05
				48.00
				176.72
				466.82
				291.65
				346.82
				63.00
				280.05
				10,749.67
				2,687.42
				8,062.25

List TotalS\$:
 25.00% Discount S\$:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CONTINUE / ...



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

ISO TEAM ACCESS PTE LTD
 8 CHANGI NORTH STREET 1
 ISOTEAM BUILDING SINGAPORE 498829

Attention : THE OWNER
 Contact : 67470220 Fax No. : 67470110

Estimate : ES007027

Date : 07/09/2020
 Vehicle Num. : GBD2653H
 Make/Model : TOYOTA HIACE-2014
 Chassis/Eng# : JTFHT02P800145783/1KD2424898
 Accident Date : 05/09/2020
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	SPECIAL NETT ITEMS :		
2.	1	REAR W/SCREEN SEALANT	65.00	65.00 ✓
3.	1	70 KM/H STICKER	15.00	15.00 ✓
4.	1	REAR NUMBER PLATE	25.00	25.00 ✓
4.	1	REVERSE SENSOR	280.00	280.00
		Special Nett Total S\$:		385.00
		LABOUR :		
		REMOVE & REINSTALL REAR W/SCREEN GLASS	180.00	180.00
		TRANSFER TAILGATE COMPONENT TO NEW GATE	150.00	150.00
		RUST PROOFING TREATMENT	100.00	100.00
		SPRAY PAINT DAMAGED AREA AFFECTED	750.00	1,200.00 ?
		COMPANY LOGO, LETTERING AND TEL NO. STICKER ON TAIL GATE	380.00	380.00 ?
		LOGO STICKER / TEL NO ON R/H REAR FENDER	300.00	300.00 ?
		TO CUT OFF REAR FENDER R/H, REAR END PANEL OUTER, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	1,800.00	1,800.00
		Labour Total S\$:		4,110.00

SingDollars : Twelve Thousand Five Hundred Fifty-Seven & Cents Twenty-Five Only

Total S\$: 12,557.25
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun