

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:


Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:



Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/11/20 Confirmed R/P @ 3764.70 with Jen. (Red 82638.30, 41%)

22/09/20 @ 7.12pm revised to Pauline Thane via Messenger by Yvonne.

Date/Time, File Pass to?

☐

Preli. Report

1) 20/11/2013

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

MER-TP

3764.70



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

not
11 SEP 2014 30 4K

not Authorized
11/9/20
The job before party.
3 days

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Hiu Choon Boon ADDRESS : 11 Chai Chee Road #03-15 Singapore 460011 TEL : 94884685		WIP : 35356 EXCESS : DATE: 4-Sep-20	
VEH NO :	SLW1424R	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1071J0133005	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 6	DATE REG.:	30-Jan-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJS1-50-221ABB	20/22	\$ 1,266.60
2	BRACKET CENTRE	1	MKD53-50-251	CNG	\$ 5.40
3	GROMMET, REAR BUMPER	4	MBHN1-50-021A	ner	\$ 10.80
4	FASTENER, REAR BUMPER	6	MB45A-56-146A	ner	\$ 18.00
5	GROMMET, REAR BUMPER	2	MH260-50-841	ner	\$ 6.00
6	TOWING COVER LHS	1	MG4YL-50-EL1 13	ner	\$ 24.90
7	REAR REINFORCEMENT	1	MGHK1-50-260	ner	\$ 538.30
8	CORD SHORT, SENSOR	1	MGMC8-67-290	ner	\$ 165.50
9	RETAINER CENTER, SENSOR	2	MKD45-67-UC5A2Y	ner	\$ 31.00
10	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 2Y	ner	\$ 361.80
11	TAPE PROTECTOR, REAR BUMPER	4	MGSD1D-50-EM1A	ner	\$ 34.40
12	GASKET LHS, TAILLAMP	1	MGJA1-51-163	ner	\$ 27.70
13	GASKET RHS, TAILLAMP	1	MGJA1-51-153	ner	\$ 27.70
14	TOWING COVER RHS	1	MG4YL-50-EK1 13	ner	\$ 24.90
TOTAL PARTS					\$ 2,543.00
TOTAL PARTS COST					\$ 2,543.00
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			660 \$ 1,320.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			630 \$ 1,260.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.			200 \$ 330.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120 \$ 250.00

5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	nn X	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	all 20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 3,860.00
TOTAL PARTS	\$ -	\$ 2,543.00
TOTAL	\$ -	\$ 6,403.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To disassemble/damage part(s) during resurvey
- Repairs are subject to confirmation
- The repairer's liability is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's warranty must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME :	Mr Hiu Choon Boon	WIP :	35356
3 ANSON ROAD		ADDRESS :	11 Chai Chee Road	EXCESS :	NIL
#16-00 SPRINGLEAF TOWER			#03-15	DATE:	4-Sep-20
SINGAPORE 079909			Singapore 460011		
ATTN. :	MOTOR CLAIMS	TEL :	94884685		
FAX :					

VEH NO :	SLW1424R	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GL1071J0133005	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 6	DATE REG.:	30-Jan-18	POLICY NO. :	

NATURE OF WORKS

Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJ51-50-221ABB	\$ 1,266.60	\$ 1,266.60
2	BRACKET CENTRE	1	MKD53-50-251	\$ 5.40	\$ 5.40
3	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.80	\$ 10.80
4	FASTENER, REAR BUMPER	6	MB45A-56-146A	\$ 18.00	\$ 18.00
5	GROMMET, REAR BUMPER	2	MH260-50-841	\$ 6.00	\$ 6.00
6	TOWING COVER LHS	1	MG4YL-50-EL1 13	\$ 24.90	\$ 24.90
7	REAR REINFORCEMENT	1	MGHK1-50-260	\$ 538.30	\$ 538.30
8	CORD SHORT, SENSOR	1	MGMC8-67-290		\$ 165.50
9	RETAINER CENTER, SENSOR	2	MKD45-67-UC5A2Y		\$ 31.00
10	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 2Y		\$ 361.80
11	TAPE PROTECTOR, REAR BUMPER	4	MG51D-50-EM1A	\$ 34.40	\$ 34.40
12	GASKET LHS, TAILLAMP	1	MGJA1-51-163	\$ 27.70	\$ 27.70
13	GASKET RHS, TAILLAMP	1	MGJA1-51-153	\$ 27.70	\$ 27.70
14	TOWING COVER RHS	1	MG4YL-50-EK1 13	\$ 24.90	\$ 24.90
TOTAL PARTS				\$ 1,984.70	\$ 2,543.00
TOTAL PARTS COST				\$ 1,984.70	\$ 2,543.00

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,320.00	
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	\$ 630.00	\$ 1,260.00	
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 200.00	\$ 330.00	
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00	

5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 1,780.00 \$ 3,860.00
			TOTAL PARTS	\$ 1,984.70 \$ 2,543.00
			TOTAL	\$ 3,764.70 \$ 6,403.00
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 3,764.70
			GST 7%	\$ 263.53 \$ -
			GRAND TOTAL	\$ 4,028.23 \$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)