

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 11 Sep 2020

Preliminary Advice

Vehicle No	: SKB7080G	Accident Date	: 06/09/2020
Make	: NISSAN TEANA	Policy No.	: PNPV2019-00008113-01
Assignment Date	: 08/09/2020	Excess	: S\$750.00
Date of Inspection	: 09/09/2020	Est. Duration of Repair	: 0
Inspection At	: CHARN'S CUSTOMCRAFT (HQ) BLOCK 1010 BUKIT MERAH LANE 3, #01-105 SINGAPORE 159724		

Point of Impact / General Description of Damages

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	27,800.00
COE / PARF Rebate	:S\$	18,981.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,819.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending investigation