

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS4/FWD20009638/PTF3E2

Date: 15/10/2020

REFERENCE

Insured/Claimant: YAP ENG KHOON Policy No: PNPV2019-00008113-01
Date of Loss: 06/09/2020 Nature of Claim: OD Claim No: 1202000020271

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB7080G**
Make & Model: NISSAN TEANA, 2.5 (A) Engine No: VQ25538498A
Reg. Date: 23/06/2011 (Man. Year: 2010) Chassis No: JN1BBUJ32Z0002825
Colour: Silver Odometer: 0 km
Engine Capacity: 2496 cc
Market Value/New Car Price: S\$23,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	750.00	-750.00	
Nett Amount (S\$)	0.00	-750.00	750.00	

INSPECTION

Date of Assignment: 08/09/2020 Present Location: Charn's Customcraft (HQ)
Date Inspected: 07/09/2020 Inspected At: Charn's Customcraft (HQ)
Block 1010 Bukit Merah Lane 3, #01-105
Singapore 159724

Estimated Period of Repair: 0.0 days

Adjuster: Sherwin Beh Swee Yang

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$23,000.00
OMV : \$29,191.00
PARF Rebate (1) : \$14,595.00
Quota Premium Paid : \$56,001.00
COE Rebate (2) : \$4,386.00
Total Rebate (1) + (2) = : \$18,981.00

The total amount incurred will be Market Value \$23,000.00 minus Total Rebate \$18,981.00 = \$4,019.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2020)
Parts: 143	NISSAN TEANA 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKB7080G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*THIS VEHICLE WAS CAUGHT IN THE FIRE. KINDLY ARRANGE A SURVEYOR TO SURVEY THE CAR.		0.00 F	*- F
					Total Parts (\$\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >