

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 48253

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0641/2020/NS
Date	:	9-Sep-20

Denise.

13773.60.

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Asit Patange
Address	:	33 Pasir Ris Link #08-30 Singapore 518154
Telephone	:	HP +65 81869587
Type of Claim	:	Own Damage Claim
Policy No.	:	1900081023-01
Vehicle No	:	SMK 2210 K
Model Code	:	Audi A4 Sedan 2.0 TFSI 8W
Model / Year	:	29-Mar-19
Engine No	:	CVK 077338
Chassis No	:	WAUZZZF43KA043723
Mileage	:	19680LM
Date In	:	7-Sep-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Sep-20
Place of Accident	:	TPE Loyang Ave Exit

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMK 2210 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓	✓
3	to dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ ✓ 480.00 ✓	✓
4	To dismantle and renew rear bumper, rear bumper spoiler and rear lid. To cut out and weld rear end panelling. Re-organise crash management components. Reinstall all parts removed.	\$ 4,200.00 2500 ✓	✓
5	To respray rear bumper, rear lid, hinges, and rear end panelling and spare wheel housing.	\$ 4,000.00 2200 ✓	✓
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>9,512.00</u>	

✓



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMK 2210 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER Distorted	\$ 2,698.00 ✓	2158.4
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ X 454.00 X	
3	REAR BUMPER SECURING STRIP <i>new</i>	\$ ✓ 220.00 ✓	176
4	REAR BUMPER SPOILER Distorted	\$ ✓ 246.00 ✓	196.4
5	REAR BUMPER TRIM <i>new</i>	\$ ✓ 289.00 ✓	230.8
6	REAR BUMPER BRACKET - RH <i>new</i>	\$ ✓ 115.00 ?	92
7	REAR LIGHT REFLECTOR - RH <i>new</i>	\$ ✓ 41.00 ✓	32.24
8	LED TAIL LIGHT - RH <i>new</i>	\$ X 1,008.00 X	
9	TAIL LIGHT TRIM - RH <i>new</i>	\$ 30.00 ? X	
10	LED TAIL LIGHT - RH <i>new</i>	\$ X 1,008.00 X	
11	TAIL LIGHT TRIM - RH <i>new</i>	\$ 30.00 ? X	
12	REAR BUMPER CARRIER <i>Best</i>	\$ 1,002.00 ✓	801.60
13	REAR BUMPER CARRIER SEAL <i>new</i> 2	\$ 28.00 ✓	22.08
14	REAR BUMPER GUIDE SECTION - RH <i>new</i>	\$ X 45.00	
15	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i> 2	\$ 44.00 X	
16	REAR BUMPER HOLDING STRAP - RH <i>new</i>	\$ ✓ 82.00	65.28
17	REAR PARKING AID SENSOR - INNER / OUTER <i>1 piece</i> 2	✓ TBC / 2	193.20
18	REAR PARKING AID SEAL RING <i>new</i> 4	\$ ✓ 14.00 ✓	10.88
19	REAR BUMPER WIRING SET <i>new</i>	\$ X 664.00 X	
20	BOOT LID CONTROL UNIT <i>new</i>	\$ X 399.00 X	
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,417.00	



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMK 2210 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	REAR LID <i>Dented</i>	\$ 2,623.00 ✓	2098.4
22	REAR LID ATTACHMENT PARTS <i>Not new</i>	\$ X 144.00 X	
23	REAR LID HINGE - LH / RH <i>Not new</i>	2 \$ ✓ 452.00 +	
24	REAR LID LOCK <i>Not new</i>	\$ X 227.00 +	
25	REAR LID LOCK STRIKER <i>Not new</i>	\$ ✓ 33.00 +	
26	ANTI THEFT GUARD COVER - INNER <i>Not new</i>	\$ X 63.00 x	
27	REAR LID FLAP GASKET <i>Not new</i>	\$ X 203.00 X	
28	PACKING ADHESIVE <i>Not new</i>	\$ ✓ 18.00 -	14.4
29	AUDI EMBLEM <i>Not new</i>	\$ ✓ 122.00 -	110.4
30	A4 INSCRIPTION <i>Not new</i>	\$ ✓ 95.00 -	75.36
31	REAR CROSS PANEL <i>Dented</i>	\$ ✓ 257.00 ✓	205.2
32	CROSS PANEL REINFORCEMENT <i>Dented</i>	\$ ✓ 499.00 ✓	398.8
33	REAR LID TRIM PANEL <i>Not new</i>	\$ X 325.00 +	
34	REAR CROSS PANEL TRIM <i>Not new</i>	\$ 164.00 X	
35	COMPARTMENT FLOOR LUGGAGE <i>Repair</i>	\$ X 703.00 +	
36	EXHAUST TAIL PIPE TRIM - RH <i>Not new</i>	\$ ✓ 350.00 -	280
37	STONE CHIP <i>Not new</i>	S/N \$ ✓ 180.00 ✓	180
38	CAVITY WAX <i>Not new</i>	S/N \$ ✓ 140.00 -	140
39	ACRYLIC SEALANT <i>Not new</i>	S/N \$ ✓ 180.00 ✓	180
40	REAR NO PLATE <i>Not new</i>	S/N \$ ✓ 60.00 ✓	60
41	SUNDRIES <i>Not new</i>	\$ ✓ 300.00 ?	40.16
TOTAL SPARE PARTS CHARGES		: \$ 15,555.00	
TOTAL LABOUR CHARGES		: \$ 9,512.00	
GRAND TOTAL		: \$ 25,067.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6368 2323 Fax : 6841 1183

Telefax

Name : Adnan Ling
Surveyed Date : 09/09/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Days
H.F.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
--

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant