

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743
ATTN: Motor Claim Department

WS Ref: TP/III/AMK
Claim Type: Third Party
Accident Date: 08/09/2020
TP Veh Reg No: SHA7213G

Estimate No: ES2090688/AMK
Date: 09 Sep 2020
Policy No: 20-MT002024-R02
Veh Reg No: SFP4134R
Make/Model: TOYOTA VOXY 2.0X CVT
Chassis No: ZRR800131865
Engine No: 3ZRB611355
Reg. Date: 01/04/2016

Estimate Repair Cost to Vehicle No :SFP4134R

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	541.20	1 PC	541.20	✓
2 REAR BUMPER RH SIDE RETAINER	160.70	1 PC	160.70	X
3 REAR BUMPER CLIP	4.50	5 PC	22.50	✓
4 REAR TAILGATE	1,812.70	1 PC	1,812.70	✓
5 TAILGATE INNER LOCK	467.00	1 PC	467.00	✓
6 TAILGATE INNER RUBBER	372.30	1 PC	372.30	✓
7 TAILGATE WINDSCREEN GLASS MOULDING	70.20	1 SET	70.20	✓
8 TAILGATE INNER TRIM BOARD	570.30	1 PC	570.30	✓
9 TAILGATE INNER HANDLE	46.90	1 PC	46.90	✓
10 REAR END PANEL	735.70	1 PC	735.70	✓
11 REAR END PANEL INNER TOP GARNISH	152.90	1 PC	152.90	✓
12 REAR END PANEL ANTENNA	136.70	1 PC	136.70	✓
13 REAR LUGGAGE COMPARTMENT INNER TOP BOARD	1,050.30	1 PC	1,050.30	✓
			6,139.40	6,139.40
Special Net				
14 REVERSE SENSOR	200.00	1 SET	200.00	✓
15 REAR BUMPER STEP GARNISH	100.00	1 PC	100.00	✓
16 REAR END PANEL SEALANT	40.00	1 PC	40.00	30ml
17 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			380.00	380.00
Labour				
18 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
19 REMOVE & REFIX REAR BUMPER, TAILLAMPS, TAILGATE, SPOILER & ATTACHMENTS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR LUGGAGE PANEL, FENDERS & REALIGN THE SAME	900.00	1 LA	900.00	700l
20 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR END PANEL, REAR LUGGAGE PANEL, FENDERS & ALL AFFECTED AREAS	800.00	1 LA	800.00	720l
21 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
22 REMOVE & REFIX REAR GARNISH, CARPET TO FACILITATE REPAIR	80.00	1 LA	80.00	60l
23 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,010.00	2,010.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/III/AMK

Claim Type: Third Party

Accident Date: 08/09/2020

TP Veh Reg No: SHA7213G

Estimate No: ES2090688/AMK

Date: 09 Sep 2020

Policy No: 20-MT002024-R02

Veh Reg No: SFP4134R

Make/Model: TOYOTA VOXY 2.0X
CVT

Chassis No: ZRR800131865

Engine No: 3ZRB611355

Reg. Date: 01/04/2016

Estimate Repair Cost to Vehicle No :SFP4134R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 8,529.40
			Add GST @ 7%	597.06
			Total Amount Payable	SS 9,126.46

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: