

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

DATE : 11 AUG 2020

CLAIM TYPE : OD CLAIM

D.O.A : 03 AUG 2020

TO : ECICSLTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

<u>S/No.</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>CONDITION /</u> <u>REMARKS</u>	<u>COST PRICE</u>	<u>TOTAL PRICE</u>
1	1	FRONT BUMPER / DR		\$ 571.90	\$ 571.90
2	1	FRONT BUMPER SIDE RETAINER RH / DR		\$ 181.00	\$ 181.00
3	1	FRONT FOG LAMP GARNISH RH / CT		\$ 130.10	\$ 130.10
4	1	FRONT BUMPER REINFORCEMENT X ML		\$ 705.00	\$ 705.00
5	1	FRONT GRILLE / DR		\$ 479.30	\$ 479.30
6	1	FRONT GRILLE EMBLEM / DR		\$ 79.90	\$ 79.90
7	1	HEADLAMP ASSY RH / DR		\$ 441.40	\$ 441.40
8	1	INTERCOOLER / DD (garnish)		\$ 165.20	\$ 165.20
9	1	INTERCOOLER GARNISH / DR		\$ 2,333.76	\$ 2,333.76
10	1	CORNER PANEL RH X R		\$ 534.60	\$ 534.60
11	1	FRONT DOOR RH X R		\$ 1,071.90	\$ 1,071.90
12	1	STEP GARNISH RH X CR		\$ 108.00	\$ 108.00
				\$ 6,802.06	\$ 6,802.06

TOTAL PRICE	\$	6,802.06
LESS 10%	\$	680.21
SUB TOTAL PRICE	\$	6,121.85

<u>S/No.</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>CONDITION / REMARKS</u>	<u>UNIT S/NETT</u>	<u>TOTAL S/NETT</u>
1	1	FRONT BUMPER CLIPS SET	✓ NK	\$ 50.00	\$ 50.00
2	1	FRONT GRILLE CLIPS SET	✓ NK	\$ 50.00	\$ 50.00
3	1	PAN PACIFIC CO. REG. STICKER	✓ NK	\$ 30.00	\$ 30.00
TOTAL S/NETT				\$ 130.00	\$ 130.00

Labour Charges

<u>Labour Charges</u>		
		\$ 800.00
1	To straighten,panel beat & align,to remove & replace damaged parts.	\$ 100.00
2	To apply anti rust coat and Tuff Kote affected areas	\$ 50.00
3	To check and rectify lighting & wiring harness	\$ 800.00
4	To Spray painting Front Portions & other affected areas.	\$ 100.00
5	To remove and transfer door components.	

TOTAL LABOUR

Total Cost of Repairs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

(Total parts + Total S/Nett + Total Labour Cost)

P-4003-34
N-89
L-1219
5293-34

L/S - 4234-67
= 4250