LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Date: 14 Sep 2020

Preliminary Advice

Insured Vehicle No : SJB2359Z

TP Vehicle No : GBK3095A Accident Date : 07/09/2020

Make : NISSAN NV350 Assignment Date : 09/09/2020

Date of Inspection : 10/09/2020 Est. Duration of Repair : 4 days

Inspection At : Efficient Motor & Engineering Works Pte Ltd (HQ)

56 Loyang Way #06-07, Loyang Enterprise Building

Singapore 508775

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,101.85
Revised Amount	:S\$	5,331.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,331.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP