

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC20P00096200	Date of Loss:	07/09/2020
Vehicle Reg. No.:	SJB2359Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOH YEW KEONG		
Driver:	LOH YEW KEONG		

Make/Model:	HONDA STREAM, 1.8 L RSZ (A)	Vehicle Reg. Date:	04/01/2008
Vehicle Colour:	Grey		
Engine No:	R18A1758065	Chassis No:	RN61051984
Odometer:	193361 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location:	VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)
-------------------	--

COST OF CLAIMS

	Amount
Parts	2,506.80
Miscellaneous Items	0.00
Labour	1,460.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	3,966.80
- Excess (S\$)	500.00
Nett Amount (S\$)	3,466.80

This claim is handled by: **THAM WEI CHUEN KENNETH**

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2020)
Parts:	M1-MPV	HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Verve Motorclinic Pte Ltd/SJB2359Z/08/09/2020 17:56	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ✓ BR	0.00	0.00	*630.00 F ✓
2	1		*FRONT GRILLE BASE ? X NN	0.00	0.00	*220.00 F
3	1		*HEADLAMP RH ✓ BR	0.00	0.00	*650.00 F ✓
4	1		*FRONT BUMPER FOG LAMP COVER ? X NN	0.00	0.00	*25.00 F
5	1		*FRONT BUMPER RETAINER RH ✓ BR	0.00	0.00	*16.00 F ✓
6	1		*FRONT BUMPER RETAINER LH ✓ BR	0.00	0.00	*16.00 F ✓
7	1		*FRONT BUMPER UPPER BRACKET RH ✓ BR	0.00	0.00	*42.00 F
8	1		*FRONT FENDER RH ✓ DD	0.00	0.00	*350.00 F ✓
9	1		*FRONT FENDER COWLING RH X NN	0.00	0.00	*80.00 F
10	10		*BUMPER CLIPS ✓ NEC	0.00	0.00	*30.00 F ✓
11	10		*COWLING CLIPS X NN	0.00	0.00	*30.00 F
12	1		*FRONT BONNET REPAIR	-20%	0.00	-
13	1		*FRONT FENDER INNER PANEL RH (REPAIR)	1353.60	0.00	0.00

F=Franchise part.

Sub Total (S\$)	2,089.00
+ Margin on L,N Items 20.00% (S\$)	417.80
Total Parts (S\$)	2,506.80

Verve Motorclinic Pte Ltd/SJB2359Z/08/09/2020 17:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK FRONT ELECTRICAL SYSTEM AND REPLACE WIRE HARNESS	New	30.00 ✓
2	TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	600.00 500 ✓
3	TO SPRAY PAINT ON AFFECTED AREA	New	800.00 700 ✓
4	ANTI RUST PROOF	New	30.00 ✓
Gross Labour Cost (S\$)			1,460.00

Verve Motorclinic Pte Ltd/SJB2359Z/08/09/2020 17:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK) 09/09/20, 1.30pm

OD - Not Authorise

Excess - ?

-P/P- L/S

Resurvey Before Spray

5 repair days

P - 1353.60

L - 1260

= 2613.60

L/S - 2090.88

= 2100