



順納隆物流私人有限公司
SNL LOGISTICS PTE LTD

Reg. No. 199407022Z GST Reg. No. 199407022-Z

Office Address : 31 GUL CIRCLE SINGAPORE 629569

Tel : 68626011 (3 Lines) Fax : 68626022

Email : snl@snl.com.sg

Quotation of repair scania new bus no: 101.PL1200.20315

Parts replacement

Structure

1. Front structure assembly. <i>X SVC</i>	1 UT	\$4007 X	} 1989 10% 1790.10
2. Rhs structure assembly. <i>bro</i>	1 UT	\$481	
3. Roof structure assembly. <i>repair</i>	1 UT	\$707 XR	
4. Front wall sealing plate assembly. <i>bt</i>	1 UT	\$134	
5. Insulation of front seal plate. <i>new</i>	1 UT	\$96	
6. Windshield wipers installation assembly. <i>cro</i>	1 UT	\$1218	
7. Front wall reinforcement assembly. <i>X SVC</i>	1 UT	\$242 X	
8. Body reinforcement plate & roof front connect (6pcs). <i>new</i>	1 UT	\$60	

Door

1. Passenger door panel assembly. <i>bt</i>	1 UT	\$1221 - 10% = 1098.90
2. Out-swing door installation assembly. <i>X SVC</i>	1 UT	\$1905 X

Glass & Others

1. Front windshield installation assembly. <i>bro</i>	1 UT	\$5074	} 10466 10% 9419.40
2. Window glass above driver window. <i>bro</i>	1 UT	\$1228	
3. Driver window assembly. <i>bro</i>	1 UT	\$1635	
4. Window glass below driver window. <i>X SVC</i>	1 UT	\$890 X	
5. RF oblique window glass. <i>bro</i>	1 UT	\$1639	
6. RC triangular glass. <i>bro</i>	1 UT	\$890	



7. Window glass on the passenger door. <i>X SVC</i>	1UT	\$1214 X
8. Window glass under the passenger door. <i>X SVC</i>	1UT	\$794 X
9. Weather bar. <i>X SVC</i>	1UT	\$41 X
9. Air instak assembly. <i>X SVC</i>	1UT	\$170 X
10. Cutter channel. <i>X SVC</i>	2UT	\$214 X

Fiberglass

1. Front external revetment assembly. <i>X SVC</i>	1UT	\$1534 X
2. Dashboard install assembly(RH). <i>de</i>	1UT	\$2603
3. Dashboard panel install assembly. <i>cut</i>	1UT	\$336
4. Internal revertment between window(part) <i>X SVC</i>	1UT	\$529 X
5. Side window curtain assembly. <i>de</i>	1UT	\$10
6. External decoration parts assembly(RH). <i>rec</i>	1UT	\$873
7. Front grill assembly. <i>X SVC</i>	1UT	\$824 X
8. Sealants. <i>rec</i>	20UT	\$500

4322
 10%
 3889.80

External lamps assembly

1. Front Headlamp(RH). <i>CRA</i>	1UT	\$593
2. Floor marker lamp. <i>X SVC</i>	1UT	\$47 X
3. Front middle outline marker lamp. <i>X SVC</i>	1UT	\$334 X
4. Reflector (RH). <i>CRA</i>	1UT	\$72

665
 10%
 598.50

Electrical Cables & Other

1. Front step install assembly. <i>repair</i>	1UT	\$593 XR
---	-----	----------



順納隆物流私人有限公司
SNL LOGISTICS PTE LTD

Reg. No. 199407022Z GST Reg. No. 199407022-Z

Office Address : 31 GUL CIRCLE SINGAPORE 629569

Tel : 68626011 (3 Lines) Fax : 68626022

Email : snl@snl.com.sg

2. Floor cover & maintenance cap assembly(parts) <i>Repair</i>	1UT	\$660 <i>X</i>
3. Front internal revertment assembly. <i>X su</i>	1UT	\$908 <i>X</i>
4. Heating defroster installation assembly. <i>nee</i>	1UT	\$644 $-10\% = 579.60$
5. Cable 11M/16M BNC/RCA Video. <i>X su</i>	1UT	\$86 <i>X</i>
6. Microphone cable. <i>X su</i>	1UT	\$98 <i>X</i>
7. Roof Harness. <i>X su</i>	1UT	\$863 <i>X</i>
8. Dashboard Harness. <i>X su</i>	1UT	\$440 <i>X</i>
9. Dashboard lower harness. <i>X su</i>	1UT	\$1084 <i>X</i>
10. Amplifier cable. <i>X su</i>	1UT	\$157 <i>X</i>
11. 5M BNC/RCA cable. <i>X su</i>	1UT	\$43 <i>X</i>
12. 10M/1M/20M/15M camera cable. <i>X su</i>	1UT	\$183 <i>X</i>
13. Antenna. <i>X su</i>	1UT	\$61 <i>X</i>
14. Air conditioner panel cable. <i>X su</i>	1UT	\$180 <i>X</i>

Total amount before gst

\$37,615



Reg. No. 199407022Z GST Reg. No. 199407022-Z
 Office Address : 31 GUL CIRCLE SINGAPORE 629569
 Tel : 68626011 (3 Lines) Fax : 68626022
 Email : snl@snl.com.sg

Labour

To supply labour to dismantle, cut & remove all the damaged & attached items to facilitate the repair and welding new structures, patch fiberglass, installation of news cables, adjust all parts alignments, complete with install for the above items.

@ 300

~~\$17,000~~ 3000

to supply labour and material to based caose, apply putty, grind and spray paint the front areas, RH side areas, complete with clear coat.

@ 300

~~\$3,000~~ 1000

4000

17376.30

4000.00

21376.30

Final total amount before gst

\$57,615

12 days
P/P

Paul
 Hp 90010068
 12 days
 P/P
 09/09/2020 @ 1540
 Resy before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: