

Section A - Accident Details

Registration Number	SHF392S
Case Reference Number	TAX/09/20/2012
Registration Date	26/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN THIAM SHING
Type of Accident	Head On
Accident Date and Time	5/9/2020 3:35 PM
Accident Reported Date and Time	7/9/2020 8:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108074
Special Instruction to ARC, if any	FRONT PORTION DAMAGE
Prepared Date and Time	7/9/2020 12:33 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$7,930.76	\$2,882.72
Total Other Cost	\$240.00	\$20.00
TOTAL COST	\$9,066.76	\$3,302.72 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	09/09/2020 8:07 AM	09/09/2020 10:29 AM
Signature		
Remarks	Total number of repair days = 2 days. SUP = 0 day.	P/P, before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2009-0284	Invoice Number	
Quotation Date	21.09.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$240.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace ✓
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Check X
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace ✓
		52127-47911	COVER, FR BUMPER RH	0.00	\$30.20	0.00	\$0.00	Replace	Not Given X
		52128-47910	COVER, FR BUMPER LH	1.00	\$30.20	25.00	\$22.65	Replace	Replace ✓
		53112-47310	GRILLE, RADIATOR	0.00	\$178.60	0.00	\$0.00	Replace	Check X
		53101-47100	GRILLE SUB-ASSY	0.00	\$422.50	0.00	\$0.00	Replace	Check X
		53111-47140	GRILLE, SUB -ASSY , 2	0.00	\$160.50	0.00	\$0.00	Replace	Check X
		51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Check X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace ✓
		52535-50060	RETAINER, FR BUMPER, LH & RH	0.00	\$8.80	0.00	\$0.00	Replace	Not Given X
		52421-47030	PAD, FRONT BUMPER (NO.1)	0.00	\$40.70	0.00	\$0.00	Replace	Not Given X
		52421-47040	PAD, FRONT BUMPER (NO.2)	0.00	\$36.00	0.00	\$0.00	Replace	Not Given X
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given X
		52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$132.70	0.00	\$0.00	Replace	Not Given X
		52611-47210	ABSORBER, FR BUMPER	0.00	\$80.20	0.00	\$0.00	Replace	Check X
		52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given X
		52103-47010	EXTENSION SUB-ASSY, LH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given X
		52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$246.10	0.00	\$0.00	Replace	Check X
		52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$716.60	0.00	\$0.00	Replace	Check X
		81185-47890	UNIT , HEADLAMP , LH	0.00	\$2,637.60	0.00	\$0.00	Replace	Check X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/09/2020

User ID : PohSuan

		81220-12240	LAMP ASSY, FOG, LH	0.00	\$237.10	0.00	\$0.00	Replace	Not Given ✓
		51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$472.40	0.00	\$0.00	Replace	Not Given X
		51447-47030	COVER, ENGINE UNDER CENTER	0.00	\$98.00	0.00	\$0.00	Replace	Not Given X
Total					\$6,793.80		\$508.87		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81185-47890	UNIT, HEADLAMP, LH	1.00	\$2,637.60	10.00	\$2,373.84	Replace	Replace
Total					2,637.60		2,373.84		

CRA

2882.72 ✓
+ 200.00 ✓
+ 220.00 ✓

3302.72 ✓

P/P

\$3,302.72

2 days