

LKK- ALG (L[Sum] JH

COMFORTDELGRO ENGINEERING PTE LTD

Date: 09.09.2020

REPAIR ESTIMATE

Time: 14:29:32

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305421641
REGN NO : SH 7744Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 09.06.2016
DATE/TIME IN : 09.09.2020 12:30
ACCIDENT DATE : 08.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER W LIP & FOG LAMP C 1 1,052.20 20.00 841.76 de ✓

0002 04-01-0103-0781-A I40VC LAMP ASSY-HEAD LH# 1 1,388.00 20.00 1,110.40 X nn

0003 04-01-0103-0574-A I40VC PANEL-FENDER LH+ 1 663.00 20.00 530.40 RY

0004 04-01-0103-0639-G I40VC BRACKET-FR BUMPER S 1 24.60 20.00 19.68 ne ✓

861.44

SUB-TOTAL : 2,502.24

JOB NATURE

0000 PB PANEL BEATING 600.00 420

0001 SP SPRAYPAINT CHARGE 500.00 400

0002 17-01 CHECK ALL LIGHTING 50.00 30

0003 20-05 RENEW ADVERTISEMENT STICKER- 100.00 (net ✓)

950.

SUB-TOTAL : 1,250.00

1811.44

4581450

2 days #

Tanpin 97495744
2 days 9/9/2020 5pm
L/S Resurvey after repair
Tanpin @ Khau B. Wn.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: