



Section A - Accident Details

Registration Number	SHC4521B
Case Reference Number	TAX/09/20/2014
Registration Date	10/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	FAN MEI SIONG
Type of Accident	Head to Rear
Accident Date and Time	5/9/2020 7:30 PM
Accident Reported Date and Time	7/9/2020 12:19 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108079
Special Instruction to ARC, if any	REAR RIGHT PORTION
Prepared Date and Time	7/9/2020 12:50 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,836.00	\$400.00
Total Spare Part Cost	\$5,970.77	\$1,216.41
Total Other Cost	\$1,260.00	(\$316.41)
TOTAL COST	\$9,911.77	\$1,600.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	11/09/2020 11:06 AM	11/09/2020 10:48 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2009-0332	Invoice Number	
Quotation Date	22.09.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR RHS PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY BATTERY PANEL	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,836.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$386.41)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
Total Other Costs	\$1,260.00	(\$316.41)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 22/09/2020

User ID PohSuan

			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace ✓
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given X
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Not Given X
		64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given X
			BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Check X
		74481-47050	BATTERY CLAMP	0.00	\$16.10	0.00	\$0.00	Replace	Not Given X
		74440-47030	BATTERY TRAY	0.00	\$42.80	0.00	\$0.00	Replace	Not Given X
		58490-47140B0	BOARD ASSY, RR RH	0.00	\$379.20	0.00	\$0.00	Replace	Not Given X
		58427-47040	SPACER, RR FLOOR	0.00	\$130.60	0.00	\$0.00	Replace	Not Given X
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check X
		81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace ✓
		61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given X
		61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair ✓
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
		65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		42611-47140	WHEEL, DISC	0.00	\$1,490.20	0.00	\$0.00	Replace	Not Given X
		62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Check X
Total					\$7,394.45		\$1,096.03		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52591-47021	BUMPER SEAL, RR RH	1.00	\$65.70	25.00	\$49.28	Replace	Replace ✓
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
Total					160.50		120.38		

✓CRA
✓CRA

1216.41
+ 300.00
+ 470.00

1986.41
- 202

1589.13

415 \$1600/-
3 days