

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
 at Workshop m/s Trans Cab
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 14 days Res.: Yes or No
 Lum Sum: 1-B.1 % 3 Val.: Yes or No

 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SPMS 552U Yr Regn: 02, 20
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toy Prins c.c. 1798
 Colour: M. Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 62.142 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTD KB 31FU X. 030 91047
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modl: NII / S/Rlm / STD / Rlm or _____
 Tyre Size: F: Sailun 195/65R15
 R: Dun
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front	Rear
R/Bal. <u>9</u> mm	R/Bal. <u>3</u> mm
L/Bal. <u>9</u> mm	L/Bal. <u>3</u> mm
D.O.A. <u>4/9/20</u>	D.O.I. <u>8/9/2020</u>

 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
& 1st
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Got BI</u>

Date/Time, File Pass to? ☐ : Prel. Report
 1) ☐ : Final Report
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S - RS. SI _____
 Extras _____
 Others _____

 TOTAL _____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS 552U

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 SEP 2020

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 ANTENNA, ELECTRICAL KEY
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 WEATHERSTRIP, BACK DOOR
- 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH
- 1 BOARD, BACK DOOR TRIM
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
- 1 LAMP ASSY, REAR, LH
- 1 LAMP ASSY, REAR, RH
- 1 PANEL ASSY, DECK TRIM SIDE, RH
- 1 BOX, DECK FLOOR, RH
- 1 BOX, DECK FLOOR, LH
- 1 BOARD, REAR FLOOR, NO.1
- 1 COVER ASSY, TONNEAU

LAD2009-001

Not Authorised
Resurvey B & paint

SMS 552U

JTDKB3FUX03091047

TOYOTA

PRIUS

4.9.2020

CHINA TAIPING

06/02/2020

LIST

\$	BT	485.60	✓
\$	B	332.70	✓
\$	mis	22.00	✓
\$	mis	374.50	✓
\$	SVC	72.00	X
\$	NSP	132.60	X
\$	NSP	132.60	X
\$	mis	39.00	✓
\$	mis	39.00	✓
\$	B	1,147.80	✓
\$	mis	913.60	✓
\$	SL	69.90	X
\$	SL	69.90	X
\$	SL	259.20	X
\$	mis	372.30	✓
\$	SL	56.50	X
\$	SL	225.20	X
\$	SL	339.60	} X
\$	SL	339.60	
\$	SL	261.00	
\$	SL	261.00	
\$	SL	293.60	
\$	SL	293.60	}
\$	SL	355.90	
\$	SL	313.60	}
\$	SL	313.00	
\$	Return	519.00	✓
\$	SVC	979.40	X

LAD2009-001

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS 552U

- 1 BOX, DECK FLOOR, REAR
- 1 PANEL ASSY, DECK TRIM SIDE, LH
- 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH
- 1 DUCT ASSY, QUARTER VENT, RH
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 TROUGH, BACK DOOR OPENING, LH
- 1 TROUGH, BACK DOOR OPENING, RH
- 1 MEMBER SUB-ASSY, SIDE, REAR RH
- 1 PANEL, ROOF SIDE, OUTER RH
- 1 PANEL, ROOF SIDE, INNER FRONT RH
- 1 REINFORCEMENT, ROOF SIDE, INNER RH
- 1 REINFORCEMENT, BACK DOOR OPENING SIDE, RH
- 1 MEMBER SUB-ASSY, SIDE, REAR LH
- 1 PANEL, ROOF SIDE, OUTER LH
- 1 PANEL, ROOF SIDE, INNER FRONT LH
- 1 REINFORCEMENT, ROOF SIDE, INNER LH
- 1 REINFORCEMENT, BACK DOOR OPENING SIDE, LH
- 1 COVER, FLOOR UNDER, NO.1
- 1 COVER, FLOOR UNDER, NO.2
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PIPE ASSY, EXHAUST, TAIL
- 1 INSULATOR, MAIN MUFFLER HEAT, RH
- 1 PAN, REAR FLOOR
- 1 EXTENSION, REAR FLOOR SIDE PANEL, RH
- 1 EXTENSION, REAR FLOOR SIDE PANEL, LH
- 1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH
- 1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH
- 1 SWITCH ASSY, BACK DOOR OPENER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH

\$	Sm	105.80	X
\$	Sm	355.90	
\$	Sm	56.50	
\$	Sm	67.00	
\$	N	871.50	
\$	N	139.80	
\$	Sm	118.30	
\$	Sm	103.40	
\$	Sm	103.40	
\$	N	288.50	X
\$	N	114.70	
\$	Sm	247.90	
\$	N	67.00	
\$	N	85.50	
\$	N	288.50	
\$	N	114.70	
\$	Sm	247.90	
\$	N	67.00	
\$	N	84.30	
\$	Sm	175.10	X
\$	CM	241.90	✓
\$	cra	229.90	✓
\$	DT	126.70	✓
\$	R	1,649.00	X
\$	N	141.00	✓
\$	B	583.40	✓
\$	N	78.30	
\$	N	78.30	
\$	N	196.50	X
\$	N	196.50	
\$	B	651.00	✓
\$	Sm	467.00	
\$	Sm	179.10	
\$	N	118.30	X
\$	N	871.50	
\$	N	139.80	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS 552U**LAD2009-001**

1 DUCT ASSY, QUARTER VENT, LH	\$	Sn	67.00	
1 SPOILER, SUB ASSY, REAR	\$	Sn	1,575.40	
1 WIRE, LUGGAGE ROOM, NO.3	\$	Sn	170.70	
1 WIRE, FLOOR, NO.2	\$	Sn	142.40	
1 WIRE, BACK DOOR, NO.2	\$	Sn	294.40	
1 WIRE, BACK DOOR, NO.1	\$	Sn	247.40	
1 LAMP SUB-ASSY, LICENSE PLATE	\$	Sn	287.80	
1 LAMP SET, STOP CENTER	\$	Sn	192.30	
1 STAY ASSY, BACK DOOR, LH	\$	Sn	242.50	X
1 STAY ASSY, BACK DOOR, RH	\$	Sn	242.50	
1 HINGE ASSY, BACK DOOR, LH	\$	N	61.00	
1 HINGE ASSY, BACK DOOR, RH	\$	N	61.00	
1 HANDLE, DOOR PULL	\$	Sn	23.40	
1 MEMBER SUB-ASSY, REAR SUSPENSION	\$	N	2,245.20	
1 MEMBER SUB-ASSY, REAR FLOOR SIDE, REAR LH	\$	N	321.40	
1 MEMBER SUB-ASSY, REAR FLOOR SIDE, REAR RH	\$	N	321.40	
1 MEMBER SUB-ASSY, REAR FLOOR SIDE, LH	\$	N	1,091.80	
1 MEMBER SUB-ASSY, REAR FLOOR SIDE, RH	\$	N	1,091.80	
1 COVER, FRONT BUMPER	\$	B	521.00	✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	Dis	110.50	✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	B	716.60	✓
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	R	246.10	X
1 ABSORBER, FRONT BUMPER, LOWER	\$	SVC	132.70	X
1 ABSORBER, FRONT BUMPER ENERGY	\$	cra	80.20	✓
1 SUPPORT, FRONT BUMPER SIDE, RH	\$	SVC	80.10	X
1 SUPPORT, FRONT BUMPER SIDE, LH	\$	SVC	82.30	X
1 COVER, ENGINE UNDER, NO.1	\$	Sn	472.40	X
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	Sn	241.90	X
1 EXTENSION, FRONT BUMPER, RH	\$	SVC	120.10	X
1 EXTENSION, FRONT BUMPER, LH	\$	SVC	120.10	X
1 COVER, FRONT BUMPER HOLE, LH	\$	Sn	30.20	X
1 COVER, FRONT BUMPER HOLE, RH	\$	Sn	30.20	✓
1 LAMP ASSY, FOG, LH	\$	Sn	237.10	X
1 LAMP ASSY, FOG, RH	\$	Sn	237.10	X
1 UNIT ASSY, HEADLAMP, LH	\$	mfg cra	2,637.60	✓
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sn	3,772.50	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS 552U**LAD2009-001**

- 1 UNIT ASSY, HEADLAMP, RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 GRILLE, RADIATOR
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 EMBLEM, SIDE PANEL
- 1 SUPPORT, RADIATOR, UPPER RH
- 1 SUPPORT, RADIATOR, UPPER LH
- 1 SUPPORT SUB-ASSY, RADIATOR, UPPER
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 BRACE, HOOD LOCK SUPPORT
- 1 GUIDE, RADIATOR AIR, NO.1 LH
- 1 GUIDE, RADIATOR AIR, NO.1 RH
- 1 GUIDE, RADIATOR AIR, NO.3
- 1 SEAL, RADIATOR TO SUPPORT, NO.3
- 1 SEAL, RADIATOR TO SUPPORT, NO.2
- 1 INLET, AIR CLEANER, NO.3
- 1 INLET, AIR CLEANER, NO.2
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER
- 1 CONDENSER ASSY, COOLER
- 1 HORN ASSY, HIGH PITCHED
- 1 HORN ASSY, LOW PITCHED
- 1 RADIATOR ASSY
- 1 WIRE, ENGINE ROOM MAIN

\$	mfg cra	2,637.60	✓
\$	sm	3,772.50	X
\$	Di	422.50	✓
\$	sm	178.60	X
\$	sm	105.80	✓
\$	sm	160.50	X
\$	sm	977.80	} X
\$	sm	202.50	
\$	sm	54.60	
\$	sm	977.80	
\$	sm	210.30	
\$	sm	54.60	
\$	sm	78.90	} X
\$	sm	78.90	
\$	sm	377.10	
\$	sm	983.10	
\$	sm	58.90	
\$	sm	58.90	} X
\$	BT sm	78.30	
\$	sm	69.90	
\$	sm	65.30	
\$	sm	112.70	
\$	sm	32.40	
\$	sm	32.60	} X
\$	sm	42.10	
\$	sm	112.70	
\$	sm	219.10	
\$	sm	292.40	
\$	SVC	1,783.20	X
\$	sm	134.80	X
\$	sm	134.80	X
\$	SVC	2,218.00	X
\$	sm	7,323.90	X
TOTAL		\$	61,255.80
25%		\$	15,313.95
		\$	45,941.85

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS 552U**LAD2009-001**

Special Nett			
1SET PARKING AID	\$	<i>Pd</i> 700.00	<i>220sn</i>
1SET REAR BUMPER CLIP	\$	<i>na</i> 85.00	<i>✓</i>
2 REAR WINDSCREEN SEALANT	\$	<i>na</i> 150.00	<i>40sn</i>
1 WINDSCREEN MOULDING	\$	<i>na</i> 200.00	<i>✓</i>
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 130.00	<i>30sn</i>
1 REAR TAILGATE TOYOTA LOGO	\$	<i>na</i> 47.90	<i>✓</i>
1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i> 54.60	<i>✓</i>
1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i> 54.60	<i>✓</i>
1 GASKET, EXHAUST PIPE	\$	<i>sn</i> 99.60	<i>X</i>
1 REAR BUMPER PROTECTOR	\$	<i>na</i> 180.00	<i>X</i>
2 SEAM SEALANT	\$	<i>na</i> 250.00	<i>X</i>
1SET BUMPER CLIP FRT	\$	<i>na</i> 80.00	<i>✓</i>
1 FRONT NUMBER PLATE WITH MOULDING	\$	<i>na</i> 200.00	<i>45sn</i>
1SET CLIP, FRONT FENDER LINER	\$	<i>na</i> 70.00	<i>X</i>
1 TYRE 195/65/15	\$	<i>sn</i> 350.00	
1SET REAR FENDER LINER CLIP	\$	<i>na</i> 70.00	
1SET FRNT BUMPER RETAINER CLIP	\$	<i>na</i> 70.00	
1SET REAR BUMPER RETAINER CLIP	\$	<i>na</i> 70.00	
1 REAR NUMBER PLATE WITH HOLDER	\$	<i>sn</i> 190.00	
1 REAR WHEEL RIM	\$	<i>sn</i> 1,879.40	
1 REAR LH WHEEL RIM COVER	\$	<i>sn</i> 211.50	
1 REAR RH WHEEL RIM COVER	\$	<i>sn</i> 211.50	
1 FRONT LH WHEEL RIM COVER	\$	<i>sn</i> 211.50	
1 FRONT RH WHEEL RIM COVER	\$	<i>sn</i> 211.50	
1 FRONT WHEEL RIM	\$	<i>sn</i> 1,879.40	
1SET REAR COMBINATION LAMP CLIP	\$	<i>na</i> 55.00	
1 END PANEL TRIM CLIP	\$	<i>na</i> 60.00	
1 REAR SPOILER CLIP	\$	<i>na</i> 60.00	
4L Radiator Coolant	\$	<i>na</i> 100.00	
TOTAL		\$	<u>7,931.50</u>
TOTAL PARTS		\$	<u>53,873.35</u>

LABOURTowing Fees \$ 170.00 *50l*

LAD2009-001

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS 552U

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	100
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	1600
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	Approx 380.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	60
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	nn 350.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	250
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	90
To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	280.00	180

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMS 552U

LAD2009-001

Putty And Spray Painting Of The Affected Portion.	\$	2,000.00	17601
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	401
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To remove and refit rear exhaust pipe to facilitate bodywork repair.	\$	170.00	601
To dismantle and refit rear axle and rear undercarriage parts, remove and renewal, final checking and testing.	\$	~ 480.00	X
To pull and jack out rear body panel and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	~ 380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	~ 380.00	X
To drop rear exhaust box and pipe, renew the same, to repair and realign front exhaust pipe.	\$	~ 250.00	X
To replace, refix and top up coolant for radiator	\$	~ 170.00	X

TOTAL \$ 10,190.00**Over All Total \$ 64,063.35**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days**30 DAYS**

18 days