



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101704

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 17/03/2021
Reference CC4/FCI20009656/Qes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLX 9594A
Insured Veh. SHC 7393J
Claim No. D20003615MFSH/1
Policy No. D-20094921MFSH
Accident Date 04/09/2020
Inspection Date 16/09/2020

Description	Total
Survey Inspection	234.00
Digital Photographs	
Transportation	
Subtotal	234.00
GST (7%)	16.38
Grand Total	250.38

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20009656/Qes3q2	
			Date: 17/03/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7393J	Veh. Inspected	SLX 9594A	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20003615MFSH/1	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	09/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104544308	Colour	SILVER	
Odometer	71932 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/09/2020	Inspection Date	16/09/2020	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 9594A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRUMPLED	556.40	556.40
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$109.30	BROKEN	218.60	218.60
1	REAR BUMPER REINFORCEMENT	BENT	399.50	399.50
1	REAR BUMPER REFLECTOR (LH)	SERVICEABLE	59.80	-
1	REAR TAIL LAMP (LH)	SERVICEABLE	379.80	-
1	REAR BOOT	TO REPAIR SEE LABOUR	739.20	-
1	REAR BOOT LOCK	JAMMED	398.20	398.20
1	REAR BOOT WEATHER STRIP	CRUMPLED	175.80	175.80
1	REAR BOOT LOGO (COROLLA)	SERVICEABLE	41.00	-
1	REAR BOOT LOGO (ALTIS)	SERVICEABLE	45.60	-
1	REAR END PANEL	DENTED	670.00	670.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	241.90	-
	LESS 20% DISCOUNT		-795.16	-
	LESS 25% DISCOUNT		-	-617.13
			3,180.64	1,851.37
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO DISMANTLE ,CUT & WELD REAR END PANEL ,CHANGE REAR BUMPER ,REAR BOOT ,REAR REINFORCEMENT ,KNOCKING ALL AREA AFFECTED BY ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR BOOT .		1,000.00	800.00
	TO PERFORM WIRE CHECKING .		20.00	20.00
	TO SPRAY REAR END PANEL ,REAR BUMPER ,REAR BOOT ,REAR REINFORCEMENT AND AFFECTED AREA.		1,000.00	600.00
			2,020.00	1,420.00
	GRAND TOTAL		5,400.64	3,471.37



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,750.00
---	--	--	-----------------

Report Ref No. CC4/FCI20009656/Qes3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLX 9594A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

