



HUA HONG PRIVATE LIMITED

250 SUNGAI KADUT STREET 1, SINGAPORE
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

09 September 2020

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON RD, #16-01
CITY HOUSE
SINGAPORE 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SLX9594A & SHC7393J ON 04/09/2020 ALONG PIE (CHANGI) AFTER
KIM KEAT LINK EXIT LANE 1 AT ABOUT 1410 HOURS

Insured : ACHMAD NASRUN BIN ABDUL KALAM
Vehicle Registration No. : SLX9594A
Vehicle Make : TOYOTA
Vehicle Model : TOYOTA COROLLA ALTIS 1.6L CVT
Vehicle Chassis No. : MR053REH104544308
Policy No. : PNPV2019-00001572-01
Date of Accident : 04/09/2020

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper / CRU		\$ 556.40
2	10	Rear Bumper Clips / Npc	\$ 5.00	\$ 50.00
3	1	Rear Bumper Side Retainer (LH/RH) / BK	\$ 109.30	\$ 218.60
4	1	Rear Bumper Reinforcement / KT		\$ 399.50
5	1	Rear Bumper Reflector (LH) / X		\$ 59.80
6	1	Rear Tail Lamp (LH) / 2		\$ 379.80
7	1	Rear Boot / X		\$ 739.20
8	1	Rear Boot Lock / Jam		\$ 398.20
9	1	Rear Boot Weather Strip / CRU		\$ 175.80
10	1	Rear Boot Logo (COROLLA) / X		\$ 41.00
11	1	Rear Boot Logo (ALTIS) / X		\$ 45.60
12	1	Rear End Panel / 2 X / PD		\$ 670.00
13	1	Rear End Panel Top Garnish / 2 X		\$ 241.90

Less 20% \$ 795.16
\$ 3,180.64

14 1 Rear Reverse Sensor / short NETT \$ 200.00

To dismantle, cut & weld rear end panel, change rear bumper, rear boot, rear reinforcement, knocking all area affected by accident \$ 1,000.00

To perform wire checking \$ 20.00

To spray rear end panel, rear bumper, rear boot, rear reinforcement and affected area \$ 1,000.00

Repair day - 4 days
L/S.

600

After PUM photo

CONTINUE NEXT PAGE

Sun Pin Chong Reg. No. 200900309M | huahong.com.sg | GST Reg. No. 200900309M
16/04/2020
TP without prejudice

Insured's Consultants hence notify the Repairer of the following:
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental claim is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

09 September 2020

QUOT202009-000009

HHTPCLAIMS20-106

**ACCIDENT INVOLVING SLX9594A & SHC7393J ON 04/09/2020 ALONG PIE (CHANGI) AFTER
KIM KEAT LINK EXIT LANE 1 AT ABOUT 1410 HOURS**

Estimate Repair List for vehicle SLX9594A - TOYOTA TOYOTA COROLLA ALTIS 1.6L CVT

S/N	Quantity	Description	Unit Price S\$	Amount S\$
				\$ 5,400.64
			7% GST	\$ 378.04
			Total	\$ 5,778.68



Authorised by Claims Dept