Official CBR Page 1 of 2

Certification for Bus Repairs

SBS Transit CBR REF NO.: HG20203467

 Depot :
 HG
 Report No.:
 W34672020
 BUS VEHICLE NO. :
 SG5420B

Driver's Co no. & Name : 77281 Tan Rui Seng

Accident Date : 02/09/2020

Date in : 03/09/2020 **Date Out :** 03/09/2020

Yr Of Reg	Make / Model	Chassis No.
2017	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P92XHA180783

Sto	Description District	Total Material cost (S\$)		
	0	\$0.00		
	TOTAL FOR PARTS			
S/N	S/N Labour / Spray Painting / Contractor Cost			
1	1 (1) Assessment of Bus (No Damage)			
2	2 Contractor's repair charges			
	TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			
	Repair cost of Advertisement / Livery	S\$ -		
	S\$ -			

Official CBR Page 2 of 2

Certification for Bus Repairs

 Depot :
 HG
 Report No.:
 W34672020
 BUS VEHICLE NO. :
 SG5420B

Driver's Co no. & Name: 77281 Tan Rui Seng

Accident Date : 02/09/2020

Date in : 03/09/2020 **Date Out :** 03/09/2020

Yr Of Reg	Mal	re / Model	Chassis No.		
2017	Volvo B9TL Eu5, DD, AC, 3 Axle		YV3S4P92XHA18078	3	
			TOTAL DAMAGE	S\$	-
			Overheads	S\$	_
			Towing Charges	S\$	-
Repair Period: 0.5 day(s)			Loss of Use	S\$	-
			TOTAL LOSS	S\$	0.00

Prepared By: Zakaria Bin Ahmad Date: 06/09/2020

Approved By

Workshop Mgr: Aw Boon Huan

Date: 08/09/2020

Survey Fee	refer to Group Claims	
TOTAL DUE	S\$	0.00

Acknowledged By

Depot Safety: Ang Kiat Siang

Date: 08/09/2020

 $[\]ensuremath{^{*}}$ This is computer generated document and does not require signature