

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

7-Sep-20

Our ref : TP/4874/20

Himalaya Pte Ltd

TPAIG

Jaslin

JTNGF3DH 908 02 4230

RE : estimate cost for vehicle no : SGV 7777Y

1 pc	rear bumper	Replaced	\$	835.00	✓
1 pc	rear bumper rh reflector	at		57.60	✓
2 pcs	rear bumper reverse sensor	Replaced 1 piece		785.60	260
1 pc	rear bumper tow hook cover	missing		56.40	✓
6 pcs	rear bumper clips	all		30.00	✓
2 pcs	rear bumper retainer	all RH.		270.00	135
1 pc	rh taillamp	all	1928	843.60	✓
1 pc	rear bumper side rh	Replaced		425.00	325
1 pc	Alphard emblem	all	1446	66.00	✓
1 pc	end panel	Replaced		798.00	✓
1 pc	rear bumper rh bracket	Dented		163.00	✓
				4,330.20	
less 25%				1,082.55	
				3,247.65	

Panel beating.

Spray painting.

Wiring.

800.00 400
~~800.00~~ 700 1130
30.00 ✓

4,877.65

Plus 7% GST

341.44

5,219.09

SD : Five thousand two hundred nineteen & cents nine only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

P/p 08/09/20

04 Days.

total: 2576 (P/p)