23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

## **Repair Estimate**

Date: 4/9/2020

Reference:

**SLR 5702M** 

Subaru /

Make:

Impreza

To Whom It May Concern

Dear Sir,

TP Alh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Name of insured .: GARY POH HUAT YEW

CHASSIS NO.: JF1GK3KC5HG003518

Date of accident.: 29/08/2020

RE: VEHICLE .: SLR 5702M

**ENGINE NO.:FB16Y662678** 

We append hereunder the estimated cost of repairs to be carried out to he Above web is Repairer

Signature:

Date:

**Parts** 

No.	Qty	Part Description	Price (SGD)			
1	1	RHF Fender R	\$ 345.00	4		

Parts Total: \$ 345.00 Less 10%: \$ 34.50

Total: \$ 310.50

Price (SGD)

Labour

Ma

**Labour Description** 

NO.			THE TOOL		
1	To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.  PER DAY)	\$	200.00	7	
2	Carry out spray painting on accident affected area	\$	200.00	L	
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	60.00	*	
4	To conduct 4 wheel alignment	\$	120.00	٢	
<u>5</u>	To remove and replace damaged under carraige parts	\$	275.00	×	
<u>6</u>	To refocus headlamp	\$	110.00	+	

Labour Total: \$ 965.00

Total: \$ 1,275.50

GST 7%: \$ 89.29

GRAND TOTAL: \$

1.364.79

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Executive Ronnie Tan

1st-Automorks38teakt6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel: 6844 1985 Fax: 6844 5185

0 | P 08 09 20