

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

PETER GN HOONG SIONG
c/o 46 Lenton Plain
Singapore 786548

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 15/10/2015

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : TOYOTA COROLLA ALTIS / SGN 8073 E		
1 pc	✓ rear boot lid LA	783.60
1 pc	✓ rear boot emblem '1.6E'	47.80
1 pc	✓ rear boot emblem 'ALTIS'	46.70
1 pc	✓ rear boot emblem 'COROLLA' } n.e.c.	54.60
1 pc	✓ rear boot emblem 'VVTi'	48.30
1 pc	✓ rear boot lock bt	251.70
1 pc	✓ rear boot lock catch R	80.50
1 pc	✓ rear boot weatherstrip dis	209.30
1 pc	✓ rear bumper def	516.70
2 pcs	✓ rear bumper bracket R	166.20
1 pc	✓ rear bumper side retainer dis.	56.30
1 pc	7 rear end panel ✓ DD	397.50
1 pc	7 rear end panel garnish ✓ CRA	218.60
2 pcs	✓ rear tail lamp assy X NN	775.20
Not Authorized HSD Rep after paint job HK Auto MPA 15/10/2015 5 - 5 weekdays s.nett		sub-total 3653.00
		less 25% 913.25
		sub-total 2739.75
1 set	reverse sensor QHWA	200 220.00
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		800 950.00
To check wiring system.		30 40.00
To spray painting on affected areas.		800 1,000.00
To remove seats, trimming to enable repair.		40 120.00
To remove and replace reverser sensor.		60 80.00
To apply rust proofing.		60 120.00
To apply waterproof sealant on welded panels.		80 120.00

5,389.75#