

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

PETER GN HOONG SIONG
c/o 46 Lenton Plain
Singapore 786548

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) mentioned in survey
is subject to final approval from Insurance Company

Date: 15/10/2015

Acknowledged by Repairer
Signature:
Date:

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE : TOYOTA COROLLA ALTIS / SGN 8073 E</u>	
1 pc	✓ rear boot lid bA	
1 pc	✓ rear boot emblem ' 1.6E '	783.60
1 pc	✓ rear boot emblem ' ALTIS '	47.80
1 pc	✓ rear boot emblem ' COROLLA ' n.e.c	46.70
1 pc	✓ rear boot emblem ' VVTi '	54.60
1 pc	✓ rear boot lock bT	48.30
1 pc	✓ rear boot lock catch R	251.70
1 pc	✓ rear boot weatherstrip dis	80.50
1 pc	✓ rear bumper def.	209.30
2 pcs	✓ rear bumper bracket R	516.70
1 pc	✓ rear bumper side retainer dis.	166.20
1 pc	✓ rear end panel ✓ DD	56.30
1 pc	✓ rear end panel garnish ✓ CRA	397.50
2 pcs	✓ rear tail lamp assy	218.60
		775.20
	Not Authorizd @ 387.60	
	HS Repair after part fixe HCAuto W.A. 15/10/2015	
	5 - 8w days s.nett	
1 set	reverse sensor chnA	
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	
	To check wiring system.	200 220.00
	To spray painting on affected areas.	800 950.00
	To remove seats, trimming to enable repair.	30 40.00
	To remove and replace reverser sensor.	800 1,000.00
	To apply rust proofing.	40 120.00
	To apply waterproof sealant on welded panels.	60 80.00
		60 120.00
		80 120.00