

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 48236**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0642/2020/NS  
**Date** : 8-Sep-20

**Vehicle NOT IN workshop. Please arrange for survey**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Ng Kok Yee  
**Address** : 52 Punggol Walk  
#05-05  
Singapore 828831  
**Telephone** : Hp +65 83160169  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1900000759  
**Vehicle No** : **SMH 1201 J**  
**Model Code** : Audi Q2 1.0 TFSI S TRONIC  
**Model / Year** : Jan-19  
**Engine No** : CHZ A91797  
**Chassis No** : WAUZZZGA0KA000753  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 6-Sep-20  
**Place of Accident** : Junction Of Punggol Way And Punggol Central

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SMH 1201 J

| S/N                  | Nature of Jobs                                                                                                                       |        | Estimated Charges            | Surveyor's Recommendations |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------|--------|------------------------------|----------------------------|
| 1                    | To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.        | S/N \$ | 280.00 X ✓                   | ✓                          |
| 2                    | To remove and transfer rhs headlight control unit and power module.                                                                  | S/N \$ | 400.00 X X                   |                            |
| 3                    | To dismantle and renew front bumper, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed. | \$     | <del>2,400.00</del> 500 1000 | ✓                          |
| 4                    | To respray front bumper, bonnet and hinges.                                                                                          | \$     | <del>2,500.00</del> 1100 ✓   | ✓                          |
| 5                    | To carry out diagnostic check.                                                                                                       | S/N \$ | 192.00 ✓ ✓                   | ✓                          |
| TOTAL LABOUR CHARGES |                                                                                                                                      | :      | \$ 5,772.00                  |                            |

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1201 J

|                               |                                               | Damage Parts & Prices     |         |
|-------------------------------|-----------------------------------------------|---------------------------|---------|
| S/N                           | Parts Description                             | S/NETT                    | REMARKS |
| 1                             | FRONT BUMPER <i>Rehnd</i>                     | \$ 1,854.00 ✓             | 1482    |
| 2                             | FRONT BUMPER FIXING PARTS ?                   | \$ nn 343.00 ? X          |         |
| 3                             | FRONT BUMPER GRILLE - CENTRE <i>Rehnd</i>     | \$ 195.00 +               |         |
| 4                             | FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i> | \$ 167.00 ✓               | 133.6   |
| 5                             | FRONT BUMPER END CAP - RH <i>Rehnd</i>        | \$ 34.00 +                |         |
| 6                             | FRONT BUMPER SPOILER ?                        | \$ 296.00 ? X nn          |         |
| 7                             | FRONT BUMPER CLOSING ELEMENT <i>Rehnd</i>     | \$ 154.00 +               |         |
| 8                             | WHEEL SPOILER - RH <i>Rehnd</i>               | \$ 34.00 +                |         |
| 9                             | RADIATOR GRILLE <i>Rehnd</i>                  | \$ 1,395.00 ✓             | 1116    |
| 10                            | RADIATOR GRILLE STRIKER PLATE ?               | \$ 123.00 ? X nn          |         |
| 11                            | FRONT BUMPER FOAM FILLER PIECE ?              | \$ ✓ 77.00 ? 61.2 cra     |         |
| 12                            | FRONT BUMPER CARRIER ?                        | \$ ✓ 679.00 ? 543.20 bent |         |
| 13                            | FRONT BUMPER COVER ?                          | \$ 99.00 ? X nn           |         |
| 14                            | CAUTION SIGN STICKER ?                        | NEC \$ 14.00 ? X nn       |         |
| 15                            | AIRCON STICKER ?                              | NEC \$ 8.00 ? X nn        |         |
| 16                            | BONNET <i>Dented</i>                          | \$ ✓ 2,757.00 ✓           | 2205.60 |
| 17                            | BONNET ATTACHMENT PARTS ?                     | \$ 163.00 ? X nn          |         |
| 18                            | BONNET LID HINGE - LH / RH ?                  | 2 \$ 122.00 +             |         |
| 19                            | BONNET STRIKER - LH / RH <i>HP</i>            | 2 \$ 218.00 +             |         |
| 20                            | BONNET SOUND ABSORBER <i>Rehnd</i>            | \$ 217.00 +               |         |
| SUB TOTAL SPARE PARTS CHARGES |                                               | : \$ 8,949.00             |         |

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMH 1201 J

|                                  |                                                        | <u>Damage Parts &amp; Prices</u> |                     |  |
|----------------------------------|--------------------------------------------------------|----------------------------------|---------------------|--|
| S/N                              | Parts Description                                      | S/NETT                           | REMARKS             |  |
| 21                               | BONNET IMPACT PROTECTION - CENTRE / LH / RH <i>new</i> | 3 \$ 90.00 ✓                     | 70.48               |  |
| 22                               | BONNET LID LOCK <i>not in</i>                          | 2 \$ 423.00 ✗                    |                     |  |
| 23                               | BONNET BOWDEN CABLE - CENTRE <i>?</i>                  | \$ 57.00 ✗                       |                     |  |
| 24                               | BONNET RELEASE ELEMENT <i>not in</i>                   | \$ 57.00 ✗                       |                     |  |
| 25                               | BONNET RELEASE LEVER                                   | \$ 13.00 ✗                       |                     |  |
| 26                               | HEADLIGHT MOUNTING - RH <i>not in</i>                  | \$ 117.00 ✗                      |                     |  |
| 27                               | LED HEADLIGHT - RH <i>not in</i>                       | \$ 4,859.00 ✗                    |                     |  |
| 28                               | LIFT CYLINDER - RH <i>not in</i>                       | \$ 141.00 ✗                      |                     |  |
| 29                               | RADIATOR AIR GUIDE - RH <i>?</i>                       | \$ 30.00 ? ✗                     | nn                  |  |
| 30                               | RADIATOR AIR GUIDE - UPPER CENTRE <i>?</i>             | \$ ✓22.00 ?                      | 17.04 deformed      |  |
| 31                               | EXTERNAL TEMPERATURE SENSOR <i>?</i>                   | \$ 56.00 ? ✗                     | nn                  |  |
| 32                               | FRONT WHEEL COVER - LH / RH <i>new</i>                 | 2 \$ 636.00 ✗                    | 508.8               |  |
| 33                               | FRONT NO PLATE <i>Dented</i>                           | S/N \$ 60.00 ✓                   | 60                  |  |
| 34                               | SUNDRIES <i>?</i>                                      | \$ 300.00 ? ✗                    | nn                  |  |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                                        | :                                | <b>\$ 15,810.00</b> |  |
| <b>TOTAL LABOUR CHARGES</b>      |                                                        | :                                | <b>\$ 5,772.00</b>  |  |
| <b>GRAND TOTAL</b>               |                                                        | :                                | <b>\$ 21,582.00</b> |  |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Ling  
Surveyed Date : 09/09/20  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 04 Days ✓

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant