



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20009684/EKyf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 12-10-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBG 7638D	<b>Veh. Inspected</b>	SGU 2704X
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2002615/THE	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	10/09/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 3	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2007
<b>Chassis No.</b>	JM6BK106270344641	<b>Colour</b>	BEIGE
<b>Odometer</b>	306357	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/50 R15	GOODYEAR	4 mm
<b>L/H Front Tyre</b>	195/50 R15	GOODYEAR	4 mm
<b>R/H Rear Tyre</b>	195/50 R15	GOODYEAR	4 mm
<b>L/H Rear Tyre</b>	195/50 R15	GOODYEAR	4 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	05/09/2020	<b>Inspection Date</b>	21/09/2020
<b>Survey held at</b>	BLK 1008 #01-24 BUKIT MERAH LANE 3		
<b>Repairer</b>	MOVA AUTOMOTIVE PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------