

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009688/UPA3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800065443

Claimant
Vehicle No : FBN5999M **Insured Vehicle No :** SMA4274R

Date of Loss: 07/09/2020 Nature of Claim: TP Claim No: 5394852083SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN5999M		
Make & Model:	HONDA CB150R, 149cc	Engine No:	KC32E0028505
Reg. Date:	12/11/2018 (Man. Year: 2018)	Chassis No:	MLHKC2884J5028505
Colour:	Green	Odometer:	26806 km
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-70 R17	Rear Tyre Size:	150-60 R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,516.40	3,515.50	3,000.90	46.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	400.00	360.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,276.40	3,915.50	3,360.90	46.19
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	7,276.40	3,100.00	4,176.40	57.40
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
Nett Liability (S\$)		3,200.00		

INSPECTION

Date of Assignment: 10/09/2020

Date Inspected: 10/09/2020 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	175.00 FL	*135.00 FL
2	1		*REAR BRAKE DISC	Not Necessary	385.00 FL	*- FL
3	1		*FRONT RIM SHAFT	Serviceable	68.00 FL	*- FL
4	1		*FRONT WHEEL RIM	Not Necessary	850.00 FL	*- FL
5	1		*HANDLE -BAR	Bent	155.00 FL	*155.00 FL
6	1		*HANDLE -BAR ENDS	O/S Scratched	90.00 FL	*30.00 FL
7	1		*SET HAND GRIPS	Torn/ Necessary	80.00 FL	*80.00 FL
8	1		*BRAKE LEVER	Scratched	65.00 FL	*65.00 FL
9	1		*SET FRONT SIGNALS	Cut	230.00 FL	*180.00 FL
10	1		*FRONT FOOTREST -R/H	Cut	75.00 FL	*75.00 FL
11	1		*FRONT FOOTREST BRACKET-R/H	Bent	245.00 FL	*190.00 FL
12	1		*BRAKE PEDAL	Cut	95.00 FL	*95.00 FL
13	1		*REAR FOOTREST -R/H	Cut	70.00 FL	*70.00 FL
14	1		*RADIATOR SIDE COVER -R/H	Cut	158.00 FL	*158.00 FL
15	1		*SET REAR SIGNAL	Cut	105.00 FL	*105.00 FL
16	1		*FRONT FOOTREST BRACKET -L/H	Not Necessary	65.00 FL	*- FL
17	1		*REAR SWING ARM	Bent	450.00 FL	*450.00 FL
18	1		*REAR RIM	Cracked	950.00 FL	*750.00 FL
19	1		*REAR RIM SHAFT	Cut	45.00 FL	*45.00 FL
20	1		*SWING ARM SHAFT	Serviceable	55.00 FL	*- FL
21	1		*REAR LAMP	Not Necessary	165.00 FL	*- FL
22	1		*TANK SIDE COVER -R/H (GREEN)	Cut	150.00 FL	*150.00 FL
23	1		*FRONT SEAT	Torn	185.00 FL	*185.00 FL
24	1		*REAR SEAT	Torn	200.00 FL	*200.00 FL
25	1		*REAR FENDER	Cut	85.00 FL	*85.00 FL
26	1		*EXHAUST PIPE	Repair	800.00 FL	*- FL
27	1		*FRONT LOWER SIDE COVER -R/H	Cut	150.00 FL	*150.00 FL
28	1		*SET MIRROR	Cut	190.00 FL	*190.00 FL
29	1		*THROTTLE CABLE	Cut	120.00 FL	*120.00 FL
30	1		*REAR FOOTREST BRACKET -R/H	Cut	80.00 FL	*72.00 FL
31	1		*SET NUMBER PLATE	Rear Bent	28.00 FS	*10.00 FS
32	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
33	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
34	1		*SET STEERING CONE	Not Necessary	95.00 FS	*- FS
35	1		*ERP I.U	Serviceable	175.00 FS	*- FS
36	1		*REAR TYRE (LOCAL PURCHASE) (\$180.00) (80%)	Cut	250.00 FS	*144.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,170.00	3,889.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	653.60	373.50
Total Parts (\$\$)	6,516.40	3,515.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	80.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	REAR SWING ARM REPLACED	New	200.00	50.00
4	TO PROVIDE LABOUR	New	400.00	300.00
Gross Labour Cost (\$\$)			760.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >