

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Ang Wee Kiat

Accident Date : 07-Sep-20

Vehicle No : FBN5999M

Vehicle Model : Honda CB150R

Manual

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender 135	C47\$ 175.00 ✓
1	Rear brake disc	11 \$ 385.00 X
1	Front rim shaft	500 \$ 68.00 X
1	Front wheel rim	11 \$ 850.00 X
1	Handle-bar	600 \$ 155.00 ✓
2	Handle-bar ends 30	9/500 \$ 90.00 ✓
1	Hand grips (1 set)	700/100 \$ 80.00 ✓
1	Brake lever	500 \$ 65.00 ✓
1	Front signals (1 set) 180	C47 \$ 230.00 ✓
1	Front footrest - R/H	C47 \$ 75.00 ✓
1	Front footrest bracket - R/H 180	300 \$ 245.00 ✓
1	Brake pedal	C47 \$ 95.00 ✓
1	Rear footrest - R/H	C47 \$ 70.00 ✓
1	Radiator side cover - R/H	C47 \$ 158.00 ✓
1	Rear signal (1 set)	C47 \$ 105.00 ✓
1	Front footrest bracket - L/H	11 \$ 65.00 X
1	rear swing arm	300 \$ 450.00 ✓
1	Rear rim 750	C47 \$ 950.00 ✓
1	Rear rim shaft	C47 \$ 45.00 ✓
1	Swing arm shaft	500 \$ 55.00 X
1	Rear lamp	11 \$ 165.00 X
1	Tank side cover - R/H (green)	C47 \$ 150.00 ✓
1	Front seat	700 \$ 185.00 ✓
1	Rear seat	700 \$ 200.00 ✓
1	Rear fender	C47 \$ 85.00 ✓
1	Exhaust pipe	11 \$ 800.00 X
1	Front lower side cover - R/H	C47 \$ 150.00 ✓
1	Mirrors (1 set)	C47 \$ 190.00 ✓
1	Throttle cable	C47 \$ 120.00 ✓
1	Rear footrest bracket - R/H 72	C47 \$ 80.00 ✓
		\$ 6,536.00
		Less 10% \$ 653.60
		\$ 5,882.40

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Ang Wee Kiat

Accident Date : 07-Sep-20

Vehicle No : FBN5999M

Vehicle Model : Honda CB150R
Manual

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	Rear / 3 set	\$	28.00	10
2	Fork oils	17	\$	30.00	X
2	Fork oil seals	17	\$	56.00	X
1	Steering cone (1 set)	17	\$	95.00	X
1	ERP I.U	50	\$	175.00	X
1	Rear tyre 1P 180	1445.2	\$	250.00	807
			\$	634.00	

S/No. Labour

1	To provide towing service	50	\$	80.00
2	To check wiring and reset headlamp focusing	17 X	\$	80.00
3	Front fork repair Rec swing arm replaced	50	\$	200.00
4	To provide labour	300	\$	400.00
			\$	760.00

Grand Total

\$ 7,276.40

Singapore Dollars: Seven Thousand Two Hundred Seventy-Six and Cents: Forty only

3915.8

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Non-legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: